

Reserve Funding Analysis Update FY2021 - 2022

for

High Desert Residential Owners Association, Inc.

December 9, 2021





Reserve Funding Analysis Update FY2021 - 2022

for

High Desert Residential Owners Association, Inc.

Table of Contents

Pages	Subject
1	 Report Cover Sheet
2	 Table of Contents
3 to 33	 Reserve Study Summary
34 to 56	 Reserve Item Summary
57 to 66	 Reserve Item Listing
67 to 69	 Cash Flow
70 to 71	 Dues Summary
72 to 89	 Revenue Report
90 to 97	 Expense Report
98 to 110	 Expense Summary



December 9, 2021

Ms. Lynnette Rodriguez HOAMCO 10555 Montgomery Boulevard NE Albuquerque, New Mexico 87111

Subject: High Desert Residential Owners Association

Dear Ms. Rodriguez:

Great Boards, LLC is pleased to present to High Desert Residential Owners Association, Inc. its requested FY2021-2022 reserve funding study update.

The following is a summary of the reserve study report for High Desert Residential Owners Association, Inc.:

Project Description

a 1,604 unit single-family home community located in Albuquerque, New Mexico. Common areas include three parks, park furniture, picnic ramadas, playground equipment, metal fencing, asphalt areas, monument signage and common area landscaping.

Client has advised that gated village entry monument signage, as well as walls and fencing that abut desert common areas will be maintained by the High Desert Residential Owners Association. Accordingly, those components that may have been included in a prior reserve study report have been removed from the inventories for all gated village reports and moved into this reserve study.

This is an update to the April 2, 2018 report prepared by Great Boards, LLC.

Date of Physical Inspection

High Desert Residential Owners Association was physically inspected by Great Boards, LLC on March 20, 2021.

Depth of Study

Reserve Study Update with Field Inspection A field inspection was made to visually verify the existing component conditions and to visually verify existing component quantities. In place testing, laboratory testing, and non-destructive testing of the reserve study components were not performed. Field measurements of some components were made to either verify improvement plan take offs or determine directly the quantities of a component. Photographs were taken of some of the site improvements.

Fiscal Year

This reserve study was prepared for the fiscal year 2021-22, beginning July 1, 2021 and ending June 30, 2022.

Initial Reserves

Initial reserves for this Reserve Study were estimated to be \$ 775,180 on July 1, 2021. An implicit assumption has been made that these reserves will not be drawn-down between the date of our estimate and the study start date.

High Desert Residential Owners Association, Inc. Funding Study Summary - Continued

Inflation Estimate

Inflation for the last year has been reviewed and a best estimate of the expected inflation for 2021 has been used to inflate future expenses.

Reserve Funding Goal

The reserve fund is set to be as close to fully funded as possible on an annual basis.

Summary of Financial Assumptions

The below table contains a partial summary of information provided by client for the High Desert Residential Owners Association, Inc. reserve funding study.

Fiscal Calendar Year Begins	July 1
Reserve Study by Fiscal Calendar Year Starting	July 1, 2021
Funding Study Length	30 Years
Number of Dues Paying Members	1604
Initial Reserves ¹	\$ 775,180
Annual Inflation Rate	2.50%
Tax Rate on Reserve Interest	0.00%
Minimum Reserve Account Balance	\$ 0
Dues Change Period	2 Years
Annual Operating Budget	\$ 0

¹ See Appendix A

Reserve Study Assumptions

The below-listed assumptions are implicit in this reserve study:

- Cost estimates and financial information are accurate and current
- No unforeseen circumstances will cause a significant reduction of reserves
- Sufficient comprehensive property insurance exists to protect from insurable risks
- The Association plans to continue to maintain the existing common areas and amenities
- Reserve payments occur at the end of every calendar month
- Expenses occur at the end of the expense year.

Impact of Component Life

The projected life expectancy of the major components and the Association's reserve funding needs are closely tied. Performing the appropriate routine maintenance for each major component generally increases component useful life, effectively moving the component expense into the future, which reduces the Association's reserve funding payments. Failure to perform such maintenance can shorten the remaining useful life of major components, bringing the replacement expense closer to the present, and increasing the Association's reserve funding payments.

Financial Condition of Association

Reserve account balance and interest rates reported by client as of February 28, 2021; plus remaining budgeted FY2020-2021 reserves contributions.

High Desert Residential Owners Association, Inc. Funding Study Summary - Continued

Special Assessments

A special assessment is not indicated during the 30-year scope of this reserve study.

Study Method

In this study, we have used the "component" method because it is the only method which allows scrutiny of the funding details. The method is pragmatic, and allows human judgment and experience to enter into the equation.

Unless otherwise noted, the present cost of every reserve item in this report has been estimated using national standards and modified by an area cost adjustment factor. Where possible, known costs have been used. In addition, every reserve item has been given an estimated remaining useful life, an estimated useful life when new, and has been cast into the future to determine the inflated cost.

Equal annual payments are calculated for each reserve item based upon a payment starting year and a payment ending year using the end of period payment method. Interest earned on accumulated reserve funds and taxes on the reserve interest are also calculated. Initial reserve funds are consumed as expenses occur until fully depleted, reducing annual reserve payments to a minimum.

Summary of Findings

Great Boards, LLC has estimated future projected expenses for High Desert Residential Owners Association, Inc. based upon preservation of existing improvements.

The attached funding study is limited in scope to those expense items listed in the attached "High Desert Residential Owners Association, Inc. Reserve Study Expense Items". Expense items which have an expected life of more than 30 Years are not included in this reserve study unless payment for these long lived items occurs within the 30 Years of the reserve study envelope.

Of primary concern is the preservation of a positive funding balance with funds sufficient to meet projected expenses throughout the study life. Based upon the attached funding study, it is our professional opinion that member monthly fees as shown in the attached "High Desert Residential Owners Association, Inc. Dues Summary" will realize this goal. Some reserve items in the "High Desert Residential Owners Association, Inc. Revenue Summary Table" may not contain payments. In this analysis the initial reserves were used to make annual payments for expense items in their order of occurrence until the initial reserve was consumed. As a result reserve items without payments may be expected, particularly in the first few years of the funding study. Reserve items that have been paid with initial reserve funds are identified with a [FP] in the Expense Items Sheets. An item marked [PR] is partially paid with initial reserve funds.

Recommended Payment Schedule

The table below contains Great Boards, LLC recommended schedule of payments for the next five years. Failure to follow the propose schedule of payments may result in inadequate High Desert Residential Owners Association reserve funds or require the use of special assessments in the future.

High Desert Residential Owners Association, Inc. Funding Study Summary - Continued

Proposed Payment Schedule

Fiscal Calend ar Year	Member Monthly Reserve Payment	Monthly Reserve Payment	Annual Reserve Payment	Proposed Reserve Balance
2021	\$ 2.24	\$ 3,588	\$ 43,056	\$ 682,852
2022	\$ 2.24	\$ 3,588	\$ 43,056	\$ 725,032
2023	\$ 2.24	\$ 3,588	\$ 43,056	\$ 763,028
2024	\$ 3.43	\$ 5,494	\$ 65,930	\$ 793,241
2025	\$ 3.43	\$ 5,494	\$ 65,930	\$ 851,884
2026	\$ 4.59	\$ 7,358	\$ 88,300	\$ 665,796

Fiscal Year begining July 1, 2021

Reserve Funding Status

Funding positions for reserve accounts generally fall into three categories. Reserves balances that fall between zero and 30% are considered "weak" as the special assessment probability of 26 to 53% is high. The second category is reserves within the 30 to 70% range. This funding position is classified as "fair" as the projected special assessment requirement is in the 3.50 to 17.60% range. When a funding position is referred to as "strong," reserves are between 70 and 100%, the risk of special assessment drops to between 2.40 and 1%.

By following the recommended payment plan, as of June 30, 2022, reserves for High Desert Residential Owners Association will be at an estimated 115.5% funding level. Accordingly, reserves for High Desert Residential Owners Association, Inc. are anticipated to be strong, and by following the recommended funding plan, the Association will have adequate funds to meet projected repair and replacement expenses.

Percent Funded

Many reserve studies use the concept of "percent funded" to measure the reserve account balance against a theoretically perfect value. Percent funded is often used as a measure of the "financial health" of an association. The assumption is, the higher the percentage, the greater the "financial health". The question of substance is simply: "how much is enough?"

To answer the question, some understanding of percent funded is required. Percent funded is the ratio of current cash reserves divided by the fully funded value at any instant in time. Fully funded is defined as the future value, multiplied by the number of years used, divided by the expected life for the sum of all reserve items. In essence, fully funded is simply the total of the average net present value of the association improvements. Percent funded is then, the current reserve balance divided by the fully funded value multiplied by 100 (to give a percentage). The concept is useful when the reserve study is comprehensive, but misleading when the reserve study is superficial or constrained. As a result, we recommend that the statement "percent funded" be used with caution.

Keeping Your Reserve Study Current

Great Boards, LLC believes that reserves funding studies are an essential part of community management. Property constantly changes and evolves, and as a result, the useful life of a reserves funding study is at best a few years, and certainly not more than five years. Accordingly, this reserve study should be updated:

- At changes in interest rates
- At changes in inflation rates
- At changes in the number of dues paying members

High Desert Residential Owners Association, Inc. Funding Study Summary - Continued

- Before starting new improvements
- Before making changes to the property
- After a flood or fire
- After the change of ownership or management
- After annexation or incorporation.

Items Beyond the Scope of this Report

Items beyond the scope of this report include:

- Building or land appraisals for any purpose
- State or local zoning ordinance violations
- Building code violations
- Soils conditions, soils contamination or geological stability of site
- Engineering analysis or structural stability of site
- Air quality, asbestos, electromagnetic radiation, formaldehyde, lead, mercury, radon, water quality or other environmental hazards
- Invasions by pests, termites and any or all other destroying organisms, insects, birds, bats or animals
 to buildings or site--this study is not a pest inspection
- Adequacy or efficiency of any system or component on site
- Specifically excluded reserve items
- Septic systems and septic tanks
- Buried or concealed portions of swimming pools, pool liners, Jacuzzis and spas or similar items
- Items concealed by signs, carpets or other things are also excluded from this study
- Missing or omitted information supplied by client for the purposes of reserve study preparation
- Hidden improvements such as sewer lines, water lines, irrigation lines or other buried or concealed items.

Cost Data Sources

The sources used to obtain cost data for the components in this report include local suppliers, the National Construction Estimator, RS Means Valuation Service, and the AFI database. The AFI database is a collection of cost data that is integrated with the AFI Professional reserve study software used by Great Boards, LLC. Wherever necessary, costs have been indexed to reflect pricing in the Albuquerque, New Mexico area.

Statement of Qualifications

Great Boards, LLC is a professional in the business of preparing reserve studies for community associations and is familiar with construction practices, construction costs, and contracting practices in the state of New Mexico. The preparer of this reserve study is a CAI-certified Reserve Study Specialist.

Conflict of Interest

As the preparer of this reserve study, Great Boards, LLC certifies that it does not have any vested interests, financial interests, or other interests that would cause a conflict of interest in the preparation of this reserve study. This reserve study is a reflection of information provided to the reserve study preparer and created for the Association's use, not for the purpose of an audit, background checks of historical records, or forensic/quality analyses. Any on-site inspection is not a project audit or quality inspection.

Great Boards, LLC would like to thank High Desert Residential Owners Association, Inc. for the opportunity to be of service in the preparation of the attached FY2021-2022 reserve study update. Please feel free to contact us by email at kerry.goto@greatboards.com, or by telephone at (602) 569-0288 with any questions regarding this report.

High Desert Residential Owners Association, Inc. Funding Study Summary - Continued

Prepared by:

Kerry-Lynn Goto, RS

Enclosures:

24 Pages of Photographs Attached APPENDIX "A" - Summary of Reserve Accounts

High Desert Residential Owners Association, Inc. Funding Study Summary - Continued



Typical parking lot asphalt at Michial Emery trailhead



Typical trail asphalt

High Desert Residential Owners Association, Inc. Funding Study Summary - Continued



Typical concrete walkway



Typical metal perimeter fencing

Prepared by Great Boards, LLC

High Desert Residential Owners Association, Inc. Funding Study Summary - Continued



Typical metal piperail fencing



Typical range fencing

High Desert Residential Owners Association, Inc. Funding Study Summary - Continued



Metal gates at Michial Emery trailhead



Chamisa Park ramada

Prepared by Great Boards, LLC

High Desert Residential Owners Association, Inc. Funding Study Summary - Continued



Pinon Point Park ramada



Typical common area stucco wall

High Desert Residential Owners Association, Inc. Funding Study Summary - Continued



"Shrine of the Bear" sculpture at Academy & Tramway



"Dance with the Planters Moon" sculpture at Spain & Tramway

High Desert Residential Owners Association, Inc. Funding Study Summary - Continued



"Blue Grama" sculptures throughout the community



Chamisa Park picnic table

High Desert Residential Owners Association, Inc. Funding Study Summary - Continued



Medara Park picnic table



Pinon Point Park picnic table

Prepared by Great Boards, LLC




Pinon Point Park play platform




Monument: Chaco Ridge & Compound

High Desert Residential Owners Association, Inc. Funding Study Summary - Continued



Monument: Chamisa Trail




Monument: Desert Highlands at High Desert

Prepared by Great Boards, LLC

High Desert Residential Owners Association, Inc. Funding Study Summary - Continued



Monument: Desert Mountain



Monument: Desert Mountain Community Pool

High Desert Residential Owners Association, Inc. Funding Study Summary - Continued



Monument: Desert Sky



Monument: Desert Song

High Desert Residential Owners Association, Inc. Funding Study Summary - Continued



Monument: High Desert



Monument: High Desert Park

High Desert Residential Owners Association, Inc. Funding Study Summary - Continued



Monument: Highlands at High Desert



Monument: Michial Emery Trailhead

Prepared by Great Boards, LLC

High Desert Residential Owners Association, Inc. Funding Study Summary - Continued



Monument: Mountain Highlands at High Desert



Monument: Overlook at High Desert

Prepared by Great Boards, LLC

High Desert Residential Owners Association, Inc. Funding Study Summary - Continued



Monument: Pinon Point



Monument: Solterra

High Desert Residential Owners Association, Inc. Funding Study Summary - Continued



Monument: Sunset Ridge



Monument: The Aerie

High Desert Residential Owners Association, Inc. Funding Study Summary - Continued



Monument: The Canyons



Monument: The Enclave

High Desert Residential Owners Association, Inc. Funding Study Summary - Continued



Monument: The Legends



Monument: The Trillium

High Desert Residential Owners Association, Inc. Funding Study Summary - Continued



Monument: Tierra del Oso



Monument: Trailhead at High Desert

High Desert Residential Owners Association, Inc. Funding Study Summary - Continued



Monument: West Highlands at High Desert



Monument: Wilderness at High Desert

High Desert Residential Owners Association, Inc. Funding Study Summary - Continued




Monument: Wilderness Canon



Monument: Wilderness Compound

High Desert Residential Owners Association, Inc. Funding Study Summary - Continued



Monument: Wilderness Estates at High Desert



Monument: Wilderness Village

Prepared by Great Boards, LLC

High Desert Residential Owners Association, Inc. Funding Study Summary - Continued



Signs: Typical hiking trail marker



Signs: Typical pet waste station

High Desert Residential Owners Association, Inc. Funding Study Summary - Continued

APPENDIX "A" Summary of Reserve Accounts

Account Description	Amount	Interest Rate	Statement Date
Remaining budgeted FY2020-2021 Reserves	\$ 19,152.50	.20%	February 28, 2021
1050 - Fidelity Master RSV MM X85-458247	\$ 137,759.05	.20%	February 28, 2021
1050.1 - Fidelity Master RSV CDs X85-458247	\$ 617,746.25	.20%	February 28, 2021
Reserve Account Total Earned Interest	\$ 522.27		July 1, 2021
Reserve Values Used :	\$ 775,180.07	.20%	July 1, 2021

Initial reserve balances have been provided by client and have not been audited for use in this report.

Evaluation of Initial Reserve Account:

Reserve account balance and interest rates reported by client as of February 28, 2021; plus remaining budgeted FY2020-2021 reserves contributions.

Initial reserve funds are contained in 3 separate funding accounts. The future value of each account was calculated based upon the account interest rate and the number of elapsed days until the study start date (July 1, 2021). The future value of the accounts was totaled and the interest rates were blended to yield a weighted average interest rate of 0.20%. The implicit assumption has been made that the reserve accounts were not drawn down between the date of the known reserve balance and the study start date.

Prepared by Great Boards, LLC High Desert Residential Owners Association, Inc. Reserve Study Expense Item Summary

Reserve Items	Current Cost When New	Estimated Remaining Life	Expected Life When New	First Replacement Cost	Repeating Item?
		Asphalt & Concre	ete		
(D) Asphalt Cracksealing & Repairs Michial Emery Trailhead	\$ 2,391	0 Years	5 Years	\$ 2,451	Yes
(D) Asphalt Cracksealing & Repairs Trail	\$ 1,500	3 Years	5 Years	\$ 1,658	Yes
(D) Asphalt Resurfacing Michial Emery Trailhead	\$ 26,998	8 Years	30 Years	\$ 33,802	Yes
(D) Asphalt Resurfacing Trail	\$ 91,760	13 Years	30 Years	\$ 130,166	Yes
(D) Asphalt Sealcoating Michial Emery Trailhead	\$ 3,024	3 Years	5 Years	\$ 3,342	Yes
(D) Asphalt Sealcoating Trail	\$ 7,608	3 Years	5 Years	\$ 8,407	Yes
(D) Concrete Sidewalks Repairs	\$ 6,000	8 Years	10 Years	\$ 7,512	Yes
		Fences & Gates	3		
(D) Fence Metal Perimeter Desert Mountain Replacement	\$ 3,042	30 Years	35 Years	\$ 6,598	No
(D) Fence Metal Perimeter Solterra Replacement	\$ 572	30 Years	35 Years	\$ 1,241	No
(D) Fence Metal Perimeter The Canyons Replacement	\$ 65,230	30 Years	35 Years	\$ 141,474	No
(D) Fence Metal Perimeter The Enclave Replacement	\$ 1,248	30 Years	35 Years	\$ 2,707	Yes
(D) Fence Metal Perimeter The Legends Replacement	\$ 1,375	30 Years	35 Years	\$ 2,982	Yes
(D) Fence Metal Perimeter The Trillium Replacement	\$ 8,224	30 Years	35 Years	\$ 17,837	Yes
(D) Fence Metal Perimeter Tierra Del Oso Replacement	\$ 31,460	30 Years	35 Years	\$ 68,232	No
(D) Fence Metal Perimeter Tramway Replacement	\$ 0.00	30 Years	35 Years	\$ 0	No
(D) Fence Metal Perimeter Wilderness Replacement	\$ 3,520	30 Years	35 Years	\$ 7,634	No
(D) Fence Metal Perimeter Wilderness Compound Replacement	\$ 2,790	30 Years	35 Years	\$ 6,050	Yes
(D) Fence Metal Pipe Rail Replacement	\$ 6,240	8 Years	25 Years	\$ 7,813	Yes

High Desert Residential Owners Association, Inc. Funding Study Expense Item Summary - Continued

Reserve Items	Current Cost When New	Estimated Remaining Life	Expected Life When New	First Replacement Cost	Repeating Item?
(D) Fence Range Open Range Replacement Future	\$ 75,000	11 Years	20 Years	\$ 101,208	Yes
(D) Gates Metal Access Replacement	\$ 12,096	32 Years	35 Years	\$ 27,578	No
(D) Gates Metal Michial Emery Trailhead Replacement	\$ 1,180	32 Years	35 Years	\$ 2,690	No
		Landscaping & Irrig	ation		
(D) Irrigation Backflow Preventers Replacement	\$ 43,500	0 Years	15 Years	\$ 44,600	Yes
(D) Irrigation Controllers Pinion Point Park Unfunded	\$ 0.00	35 Years	35 Years	\$ 0	No
(D) Irrigation Controllers Replacement	\$ 20,000	0 Years	10 Years	\$ 20,506	Yes
(D) Irrigation Flow Meters Replacement	\$ 4,500	0 Years	15 Years	\$ 4,614	Yes
(D) Irrigation Lateral Line Replacement	\$ 15,000	0 Years	15 Years	\$ 15,379	Yes
(D) Irrigation Main Line Replacement	\$ 107,905	15 Years	30 Years	\$ 160,908	Yes
(D) Irrigation Spray Heads Replacement	\$ 1,125	3 Years	5 Years	\$ 1,243	Yes
(D) Irrigation System Common Area Allowance	\$ 5,000	3 Years	10 Years	\$ 5,525	Yes
(D) Irrigation System Pinion Point Park Replacement	\$ 16,500	8 Years	30 Years	\$ 20,658	Yes
(D) Irrigation Valve Boxes Replacement	\$ 11,385	8 Years	10 Years	\$ 14,254	Yes
(D) Irrigation Valves Replacement	\$ 139,150	5 Years	7 Years	\$ 161,644	Yes
(D) Irrigation Water Meters Replacement	\$ 72,500	5 Years	20 Years	\$ 84,220	Yes
(D) Landscape Decomposed Granite Refurbishment	\$ 1,000	0 Years	2 Years	\$ 1,025	Yes
(D) Landscaping Plant Material Replacement	\$ 20,000	7 Years	10 Years	\$ 24,423	Yes
(D) Landscaping Turf Pinion Point Park Replacement	\$ 21,000	0 Years	5 Years	\$ 21,531	Yes

High Desert Residential Owners Association, Inc. Funding Study Expense Item Summary - Continued

Reserve Items	Current Cost When New	Estimated Remaining Life	Expected Life When New	First Replacement Cost	Repeating Item?
		Lighting			
(D) Accent Lights Replacement	\$ 1,885	4 Years	10 Years	\$ 2,136	Yes
		Painting & Repai	rs		
(D) Metal Fences and Gates Painting	\$ 25,775	0 Years	7 Years	\$ 26,427	Yes
(D) Ramada Chamisa Park Refurbishment	\$ 2,170	1 Years	25 Year	\$ 2,281	Yes
(D) Ramada Pinon Point Park Refurbishment	\$ 1,682	2 Years	25 Years	\$ 1,813	Yes
(D) Stucco Walls Painting	\$ 161,115	8 Years	10 Years	\$ 201,721	Yes
(D) Stucco Walls Repairs	\$ 10,740	8 Years	10 Years	\$ 13,447	Yes
	F	Park Furniture & Elei	ments		
(D) Art Restoration	\$ 2,700	5 Years	20 Years	\$ 3,136	Yes
(D) Park Furniture Chamisa Park Replacement	\$ 1,125	30 Years	35 Years	\$ 2,440	No
(D) Park Furniture Medara Park Replacement	\$ 2,300	30 Years	35 Years	\$ 4,988	No
(D) Park Furniture Pinion Point Park Replacement	\$ 800	30 Years	35 Years	\$ 1,735	No
(D) Play Equipment Pinion Point Park Replacement	\$ 16,380	8 Years	15 Years	\$ 20,508	Yes
		Signage			
(D) Monument Chaco Ridge & Compound Refurbishment	\$ 375	2 Years	12 Years	\$ 404	Yes
(D) Monument Chamisa Trail Refurbishment	\$ 375	2 Years	12 Years	\$ 404	Yes
(D) Monument Desert Highlands at High Desert Refurbishment	\$ 5,000	6 Years	12 Years	\$ 5,955	Yes
(D) Monument Desert Mountain at High Desert Refurbishment	\$ 750	6 Years	12 Years	\$ 893	Yes
(D) Monument Desert Sky Refurbishment	\$ 375	2 Years	12 Years	\$ 404	Yes
(D) Monument Desert Song Refurbishment	\$ 375	2 Years	10 Years	\$ 404	Yes

High Desert Residential Owners Association, Inc. Funding Study Expense Item Summary - Continued

Reserve Items	Current Cost When New	Estimated Remaining Life	Expected Life When New	First Replacement Cost	Repeating Item?
(D) Monument High Desert Refurbishment	\$ 20,000	6 Years	10 Years	\$ 23,821	Yes
(D) Monument High Desert Park Refurbishment	\$ 5,000	3 Years	10 Years	\$ 5,525	Yes
(D) Monument Highlands at High Desert Refurbishment	\$ 5,000	6 Years	12 Years	\$ 5,955	Yes
(D) Monument Michial Emery - Bear Canyon Trailhead Replacement	\$ 375	8 Years	12 Years	\$ 470	Yes
(D) Monument Mountain Highlands at High Desert Refurbishment	\$ 5,000	6 Years	12 Years	\$ 5,955	Yes
(D) Monument Overlook at High Desert Refurbishment	\$ 5,000	6 Years	12 Years	\$ 5,955	Yes
(D) Monument Pinon Point Refurbishment	\$ 430	2 Years	12 Years	\$ 463	Yes
(D) Monument Solterra Refurbishment	\$ 375	6 Years	12 Years	\$ 447	Yes
(D) Monument Sunset Ridge Refurbishment	\$ 375	2 Years	12 Years	\$ 404	Yes
(D) Monument The Aerie Refurbishment	\$ 375	7 Years	12 Years	\$ 458	Yes
(D) Monument The Canyons at High Desert Refurbishment	\$ 375	9 Years	12 Years	\$ 481	Yes
(D) Monument The Enclave at High Desert Refurbishment	\$ 425	7 Years	10 Years	\$ 519	Yes
(D) Monument The Legends at High Desert Refurbishment	\$ 430	2 Years	12 Years	\$ 463	Yes
(D) Monument The Trillium at High Desert Refurbishment	\$ 430	0 Years	15 Years	\$ 441	Yes
(D) Monument Tierra Del Oso Refurbishment	\$ 285	2 Years	12 Years	\$ 307	Yes
(D) Monument Trailhead at High Desert Refurbishment	\$ 5,000	6 Years	12 Years	\$ 5,955	Yes
(D) Monument West Highlands at High Desert Refurbishment	\$ 5,000	6 Years	12 Years	\$ 5,955	Yes
(D) Monument Wilderness At High Desert Refurbishment	\$ 430	6 Years	12 Years	\$ 512	Yes

High Desert Residential Owners Association, Inc. Funding Study Expense Item Summary - Continued

Reserve Items	Current Cost When New	Estimated Remaining Life	Expected Life When New	First Replacement Cost	Repeating Item?
(D) Monument Wilderness Canon Refurbishment	\$ 375	12 Years	15 Years	\$ 519	Yes
(D) Monument Wilderness Compound Refurbishment	\$ 375	12 Years	15 Years	\$ 519	Yes
(D) Monument Wilderness Estates at High Desert Refurbishment	\$ 5,000	4 Years	10 Years	\$ 5,665	Yes
(D) Monument Wilderness Village Refurbishment	\$ 375	2 Years	12 Years	\$ 404	Yes
(D) Signs Hiking Trail Replacement	\$ 10,500	3 Years	20 Years	\$ 11,603	Yes
(D) Signs Pet Waste Stations Replacement	\$ 17,500	30 Years	35 Years	\$ 37,955	Yes

Missing table information is identical to the first printed information above.

Months Remaining in Fiscal Calendar Year 2021: 12

Expected annual inflation: 2.50% Interest earned on reserve funds: 0.20%

Initial Reserve: \$ 775,180

(D) Indicates Tabulated Reserve Item Description.

Reserve Item Descriptions

Category	Reserve Item Name	Reserve Item Description
		Client advised that significant patching and cracksealing were performed in 2014 at a cost of:
		Cracksealing (hot rubber) and jointsealing: \$1,095.00
		Patching: \$1,296.00
Asphalt & Concrete	Asphalt Cracksealing & Repairs Michial Emery Trailhead	Accordingly, we increased the reserves amount for this component to \$2,391 for future cycles. At client's request, we increased the remaining useful life of this component to 5 years in the 2016 reserve study update.
		Cost source: Client Funding has been included for cracksealing and minor repairs in conjunction with
	Asphalt Cracksealing & Repairs Trail	each asphalt sealcoating cycle.
		Cost source: Sunland Asphalt

High Desert Residential Owners Association, Inc. Funding Study Expense Item Summary - Continued

Category	Reserve Item Name	Reserve Item Description
		Component consists of overlay on parking lot asphalt. For inventory purposes, this component consists of:
	Asphalt Resurfacing Michial	Overlay: 17,070 sq. ft. @ \$1.40 sq. ft.
	Emery Trailhead	Restriping: \$100
		Equipment mobilization: \$3,000
		Cost source: Sunland Asphalt
		Component consists of overlay on trail asphalt. For inventory purposes, this component consists of:
	Asphalt Resurfacing Trail	Overlay: 63,400 sq. ft. @ \$1.40 sq. ft.
		Equipment mobilization: \$3,000
		Cost source: Sunland Asphalt
		Client advised that sealcoating and restriping were performed in 2014 at a cost of:
Asphalt & Concrete		Sealcoating (Master Seal-MTR): \$2,669.00
	Asphalt Sealcoating Michial	Striping: 355.00
	Emery Trailhead	Accordingly, we increased the reserves amount for this component to \$3,024.00 for future cycles.
		Cost source: Client
	Asphalt Sealcoating Trail	Component consists of sealcoating approximately 63,400 sq. ft. of trail asphalt.
		Cost source: Sunland Asphalt
		Funding has been included for repairs or replacements of the community's concrete sidewalks at a rate of 500 sq. ft. every 10 years.
	Concrete Sidewalks Repairs	Client advised that \$457.08 was spent in 2014 for concrete sidewalk repairs at Cortaderia & Spain.
		Cost source: National Construction Estimator

High Desert Residential Owners Association, Inc. Funding Study Expense Item Summary - Continued

Category	Reserve Item Name	Reserve Item Description
		This component consists of approximately:
		2 - 3'6" x 6' metal pedestrian access gates @ \$26 sq. ft.
	Fence Metal Perimeter	12 - lin. ft. of 6' high metal fencing @ 28.50 lin. ft.
	Desert Mountain Replacement	At client's request, these components have been moved to this report from the prior Desert Mountain reserve study.
		Cost source: Prior report
		Component consists of approximately 26 lin. ft. of 5' metal fencing. This fencing should be painted regularly to extend its useful life.
	Fence Metal Perimeter Solterra Replacement	At client's request, we increased the useful life and remaining useful life of this component to 35 years in the 2016 reserve study update.
Fences & Gates		Cost source: National Construction Estimator
rences & Gales		Component consists of approximately 2,965 lin. ft. of 5' metal fencing. This fencing should be painted regularly to extend its useful life.
	Fence Metal Perimeter The Canyons Replacement	At client's request, we increased the useful life and remaining useful life of this component to 35 years in the 2016 reserve study update.
		Cost source: National Construction Estimator
		This component consists of approximately:
		30 lin. ft. of 6' high metal fencing @ \$28.60 lin. ft.
	Fence Metal Perimeter The	1 - 3' x 5' metal pedestrian gate @ \$26.00 sq. ft.
	Enclave Replacement	At client's request, these components have been moved to this report from the prior Enclave reserve study.
		Cost source: Prior report

High Desert Residential Owners Association, Inc. Funding Study Expense Item Summary - Continued

Category	Reserve Item Name	Reserve Item Description
		This component consists of approximately:
	Fence Metal Perimeter The	50 lin. ft. of 3' metal fencing @ \$17.60 lin. ft. 2 - 3' x 5' pedestrian access gates @ \$16.50 sq. ft.
	Legends Replacement	At client's request, these components have been moved to this report from the prior Enclave reserve study.
		Cost source: Prior report
		This component consists of approximately:
		290 lin. ft. of 5' metal fencing @ \$23.75 lin. ft.
		1 - 3' x 5' pedestrian access gate @ \$16.50 sq. ft.
	Fence Metal Perimeter The Trillium Replacement	3 - 4' x 5'6" pedestrian gates @ \$16.50 sq. ft.
		At client's request, these components have been moved to this report from the prior Enclave reserve study.
		Cost source: Prior report
Fences & Gates		Component consists of approximately 1,430 lin. ft. of 5' metal fencing. This fencing should be painted regularly to extend its useful life.
	Fence Metal Perimeter Tierra Del Oso Replacement	At client's request, we increased the useful life and remaining useful life of this component to 35 years in the 2016 reserve study update.
		Cost source: National Construction Estimator
		Component consists of approximately 120 lin. ft. of 5' metal fencing. This fencing should be painted regularly to extend its useful life.
	Fence Metal Perimeter Tramway Replacement	At client's request, we increased the useful life and remaining useful life of this component to 35 years in the 2016 reserve study update.
		Cost source: National Construction Estimator
		Component consists of approximately 160 lin. ft. of 5' metal fencing. This fencing should be painted regularly to extend its useful life.
	Fence Metal Perimeter Wilderness Replacement	At client's request, we increased the useful life and remaining useful life of this component to 35 years in the 2016 reserve study update.
		Cost source: National Construction Estimator

High Desert Residential Owners Association, Inc. Funding Study Expense Item Summary - Continued

Category	Reserve Item Name	Reserve Item Description
	Fence Metal Perimeter Wilderness Compound Replacement	This component consists of approximately: 43 lin. ft 4' high metal fencing @ \$19.80 lin. ft. 82 lin. ft 3' high metal fencing @ \$17.60 lin. ft. 2 - 3' x 5' pedestrian access gates @ \$16.50 sq. ft. At client's request, these components have been moved to this report from the prior Enclave reserve study. Cost source: Prior report
	Fence Metal Pipe Rail Replacement	Component consists of approximately 240 lin. ft. of 2-pipe rail fencing bordering walkways and drainage areas. This fencing should be painted regularly to extend its useful life.
		Cost source: National Construction Estimator
Fences & Gates	Fence Range Open Range Replacement Future	Funding has been included for future replacement of approximately 19,200 lin. ft. of range-style post and wire fencing on a 20-year cycle. Client advised that approximately 700 lin. ft. of post and wire fencing was installed in 2017 at the Trailhead neighborhood bordering Glenwood Hills.
		Cost source: Client
		Component consists of the following gates:
		13 - 3' x 5' pedestrian access gates @ \$240 ea.
		4 - 10' vehicular access gates @ \$2,244 ea.
		These gates should be painted regularly to extend their useful life.
	Gates Metal Access Replacement	These gates are located throughout the community, and are used by landscape maintenance personnel to access open-space areas within the community.
		At client's request, we increased the useful life and remaining useful life of this component to 35 years in the 2016 reserve study update.
		Some rusting was noted on these gates during our September 6, 2017 site visit. This should be addressed immediately to prolong the useful life of the metal.
		Cost source: National Construction Estimator

High Desert Residential Owners Association, Inc. Funding Study Expense Item Summary - Continued

Category	Reserve Item Name	Reserve Item Description
Fences & Gates	Gates Metal Michial Emery Trailhead Replacement	Component consists of the following gates: 2 - 12.5' metal gates At client's request, we increased the useful life and remaining useful life of this component to 35 years in the 2016 reserve study update. Cost source: National Construction Estimator
	Irrigation Backflow Preventers Replacement	At client's request, funding has been included for replacement of 29 irrigation backflow preventers at a cost of \$1,500 each on a 15-year cycle. For purposes of this report, we have used 2006 as the original placed-in-service date for this component. Cost source: Client
	Irrigation Controllers Pinion Point Park Unfunded	The community's landscape maintenance contractor advised that this timeclock replacement was included in the 2010 master association replacement for irrigation controllers, and that the Pinion Point Park's irrigation is now controlled by the master association.
	Irrigation Controllers Replacement	At client's request, funding has been included for replacement of 8 irrigation controllers at a cost of \$2,500 each on a 10-year cycle. For purposes of this report, we have used 2010 as the placed-in-service year for this component.
		Cost source: Client
Landscaping & Irrigation	Irrigation Flow Meters Replacement	At client's request, funding has been included for replacement of 3 irrigation flow meters at a cost of \$1,500 each on a 15-year cycle. For purposes of this report, we have used 2006 as the original placed-in-service year for this component.
		Cost source: Client
	Irrigation Lateral Line Replacement	At client's request, funding has been included for replacement of 7,500 lin. ft. of irrigation lateral line at a cost of \$2.00 lin. ft. on a 15-year cycle. For purposes of this report, we have used 2006 as the original placed-in-service year for this component. Cost source: Client
	Irrigation Main Line Replacement	At client's request, funding has been included for replacement of 30,830 lin. ft. of irrigation main line at a cost of \$3.50 lin. ft. on a 30-year cycle. For purposes of this report, we have used 2006 as the original placed-in-service year for this component. Cost source: Client

High Desert Residential Owners Association, Inc. Funding Study Expense Item Summary - Continued

Category	Reserve Item Name	Reserve Item Description
	Irrigation Spray Heads Replacement	At client's request, funding has been included for replacement of 225 irrigation spray heads at a cost of \$5.00 each on a 5-year cycle. For purposes of this report, we have used 2019 as the replacement year for this component.
		Cost source: Client
	Irrigation System Common Area Allowance	Client advised that the former common area irrigation and drip systems were replaced in 2010 with a 2-wire system at a cost of approximately \$200,000. For purposes of this report, we have included \$5,000 in funding every 10 years for major repairs.
	Alea Allowalice	Client advised that \$3,745.00 was spent in 2014 for irrigation repairs.
		Cost source: Client
		Component consists of:
Landscaping & Irrigation	Irrigation System Pinion Point Park Replacement	1 - drip irrigation system @ \$8,250 1 - turf irrigation system @ \$8,250
		Cost source: Benjamin Miller, Heads Up Landscape Contractors
	Irrigation Valve Boxes Replacement	At client's request, funding has been included for replacement of 253 irrigation valve boxes at a cost of \$45.00 each on a 10-year cycle. For purposes of this report, we have used 2019 as the replacement year for this component.
		Cost source: Client
	Irrigation Valves Replacement	At client's request, funding has been included for replacement of 253 irrigation valves at a cost of \$550 each on a 7-year cycle. For purposes of this report, we have used 2019 as the replacement year for this component.
		Cost source: Client
	Irrigation Water Meters Replacement	At client's request, funding has been included for replacement of 29 water meters at a cost of \$2,500 each on a 20-year cycle. For purposes of this report, we have used 2006 as the original placed-in-service date for this component.
		Cost source: Client

High Desert Residential Owners Association, Inc. Funding Study Expense Item Summary - Continued

Category	Reserve Item Name	Reserve Item Description
	Landscape Decomposed Granite Refurbishment	Component consists of decomposed granite refurbishment at garden area. The community's landscape maintenance contractor has advised that refurbishment of decomposed granite generally occurs after heavy rains, and that the the cost for this erosion remediation at High Desert is approximately \$1,000 every 2 years. Client has advised that \$928.76 was spent in 2014 for backfill at the Lengends wall.
		Cost source: Benjamin Miller, Heads Up Landscape Contractors
Landscaping & Irrigation	Landscaping Plant Material Replacement	Component includes replacement of plants, trees, bushes and sod, if necessary. The community's landscape maintenance contractor has advised that the cost of the current replacement for the Spain & Academy entryway is approximately \$20,000. For purposes of this report, we have used \$20,000 as the replacement cost.
		Cost source: Benjamin Miller, Heads Up Landscape Contractors
	Landscaping Turf Pinion Point Park Replacement	Prior reserve study allowed for 100 sq. ft. of turf replacement. The Association's landscape maintenance contractor has advised that this high-traffic area is closer to 1,000 sq. ft. For purposes of this report, we have increased the replacement area by 900 sq. ft.
		At client's request, we increased the remaining useful life of this component to 5 years in the 2016 reserve study update.
		Cost source: Benjamin Miller, Heads Up Landscape Contractors
Lighting		Component consists of: 13 - signage up-lights
	Accent Lights Replacement	located at the "High Desert" monument signage areas at the community entryways.
		Client advised that \$466.18 was spent in 2014 for monument lighting replacement.
		Cost source: AFI Database

High Desert Residential Owners Association, Inc. Funding Study Expense Item Summary - Continued

Category	Reserve Item Name	Reserve Item Description
		Funding has been included for periodic painting of the metal fencing throughout the community. Metal fencing should be repainted regularly to prevent rusting and extend its useful life. For inventory purposes, there is approximately 31,855 sq. ft. of metal fencing.
	Metal Fences and Gates Painting	Client advised that the community's view fencing was painted in 2014 at a total cost of \$25,774.64, and we have used this amount as the basis for future repainting. Cost source: Client
Painting & Repairs	Ramada Chamisa Park Refurbishment	Component consists of one 12' x 24' stucco ramada with wood trellis shade structure. Refurbishment includes stucco repairs and painting, and removal and replacement of the wood trellis.
	Ramada Pinon Point Park Refurbishment	Cost source: National Construction Estimator Component consists of one 12' x 14' stucco ramada with wood trellis shade structure. Refurbishment includes stucco repairs and painting, and removal and replacement of the wood trellis. Cost source: National Construction Estimator
	Stucco Walls Painting	Component consists of repainting of approximately 268,525 sq ft. of common area stucco walls.
		Cost source: Advanced Painting & Contracting

High Desert Residential Owners Association, Inc. Funding Study Expense Item Summary - Continued

Category	Reserve Item Name	Reserve Item Description
		Total common area stucco wall Inventory consists of approximately 268,525 sq. ft Funding has been included for repairs to 2% of the total stucco wall area in conjunction with each painting cycle.
		Client advised that the following repairs were performed during 2014-2015:
		2014 - Common wall repairs: \$1,850.93
		2014 - Master wall repairs: \$2,926.43
		2014 - Outer wall repairs: \$4,060.01
		2015 - Bridge wall/barricade: \$1,346.52
		2015 - Common wall project: \$21,000.00
Painting & Repairs	Stucco Walls Repairs	2015 - Wall repair 41 Tramway: \$34,121.52
		2015 - South wall stucco repairs: \$4,066.00
		2015 - North wall repairs: \$4,922.00
		Client has advised that \$112,663 was spent in FY2017-18 for stucco wall repairs.
		Client has advised that \$33,787.01 was spent in FY2018-19 for stucco repairs.
		Client has advised that \$72,359.58 was spent in FY2020-21 for stucco wall repairs/replacements.
		Cost source: Advanced Painting & Contracting
Park Furniture & Elements	Art Restoration	This component consists of the two large sculputures; one at each of the Academy and Spain community entryways.
		The piece at the Academy entrance is titled "Shrine to the Bear" and it pays homage to the bears of Bear Canyon. It also looks like blue grama grass as it's about to release a seed head. The piece at the Spain entrance is titled "Dance With the Planter's Moon" and looks like the more familiar form of blue grama grass with the seed head just beginning to curl.
		The replacement value of each is \$150,000, per the artist, Ali Baudoin, in 2011. While the artist has stated there should be no restoration work on the sculptures, we are reserving \$1,350 per sculpture for restoration on a 20-year cycle.
		At client's request, we increased the remaining useful life of this component to 10 years in the 2016 reserve study update.
		Cost source: Prior reserve study

High Desert Residential Owners Association, Inc. Funding Study Expense Item Summary - Continued

Category	Reserve Item Name Reserve Item Description						
		Component consists of:					
		1 - concrete picnic table @ \$800					
		1 - 6' wood bench @ \$225					
	Park Furniture Chamisa Park	Although the concrete picnic table should last the life of the project, we have included replacement funding due to the risk of vandalism.					
	Replacement	At client's request, we increased the useful life and remaining useful life of this component to 35 years in the 2016 reserve study update.					
		The concrete picnic table was in need of refinishing and the wood bench seats were in need of replacement during our September 6, 2017 site visit.					
		Cost source: AFI Database					
Park Furniture & Elements		Component consists of:					
		4 - stone tables @ \$475 ea.					
	Park Furniture Medara Park	4 - display message walls @ \$100 ea.					
	Replacement	At client's request, we increased the useful life and remaining useful life of this component to 35 years in the 2016 reserve study update.					
		Cost source: AFI Database					
		Component consists of one concrete picnic table with benches. Although this concrete table should last the life of the project, replacement funding has been included due to the threat of vandalism.					
	Park Furniture Pinion Point Park Replacement	At client's request, we increased the useful life and remaining useful life of this component to 35 years in the 2016 reserve study update.					
		Cost source: AFI Database					

High Desert Residential Owners Association, Inc. Funding Study Expense Item Summary - Continued

Category	Reserve Item Name	Reserve Item Description
		Component consists of:
		1 - 5-unit play platform @ \$8,800
		1 - play structure @ 5,600
		4 - spring riders @ \$495 ea.
Park Furniture & Elements	Play Equipment Pinion Point Park Replacement	Client advised that the following work was performed at the Pinion Park playground in 2014:
		Play equipment upgrades: \$2,701.75
		Installation: \$2,043.75
		Cost source: Playworld Systems
		Component consists of 22 sq. ft. of split-faced block wall with metal lettering on each side (two-sided sign). Refurbishment consists of block repairs and painting, and metal lettering cleaning and minor repairs.
	Monument Chaco Ridge & Compound Refurbishment	Client has advised that monument signage for all gated parcels will be maintained by the High Desert Residential Owners Association in accordance with the Association's "Gated Village Maintenance Policy."
		Cost source: National Construction Estimator
	Monument Chamisa Trail Refurbishment	Component consists of 22 sq. ft. of split-faced block wall with metal lettering on each side (two-sided sign). Refurbishment consists of block repairs and painting, and metal lettering cleaning and minor repairs.
Signage		Cost source: National Construction Estimator
		Component consists of one sign consisting of approximately 48 sq. ft. of stucco over block with metal lettering and artwork.
	Monument Desert Highlands at High Desert Refurbishment	Ali Baudoin, the artist who created this sign, has estimated the replacement cost at approximately \$7,500. The sign may require some refurbishment such as reaffixing lettering and replacing mounts, and estimates this cost to be approximately \$5,000.
		Client advised that plants, irrigation lines and solar lighting were added to this signage in 2012.
		Cost source: Ali Baudoin

High Desert Residential Owners Association, Inc. Funding Study Expense Item Summary - Continued

Category	Reserve Item Name	Reserve Item Description
		This component consists of:
		2 - double-sided stone signs with metal lettering 4 - accent lights
	Monument Desert Mountain at	Refurbishment includes cleaning of stone and minor repairs or replacements of metal lettering and lighting.
	High Desert Refurbishment	Some paint deterioration was noted on the sign lettering during our September 6, 2017 site visit.
		Client has advised that monument signage for all gated parcels will be maintained by the High Desert Residential Owners Association in accordance with the Association's "Gated Village Maintenance Policy."
		Cost source: National Construction Estimator
Signage	Monument Desert Sky Refurbishment	Component consists of 22 sq. ft. of split-faced block wall with metal lettering on each side (two-sided sign). Refurbishment consists of block repairs and painting, and metal lettering cleaning and minor repairs.
		Cost source: National Construction Estimator
	Monument Desert Song Refurbishment	Component consists of a 4' diameter ceramic tile sign. This sign was in excellent condition at the time of our site visit. Accordingly, we have increased the remaining useful life for this component by 5 years. Refurbishment cleaning tile surfaces, and repairs to tile surfaces.
		Cost source: National Construction Estimator
		Component consists of four monument signs, consisting of a total of 90 lin ft. of 5'8" high stucco wall with 18" metal letters and 5' emblem.
	Monument High Desert Refurbishment	Ali Baudoin, the artist who created this signage, has estimated the replacement cost for each sign at approximately \$7,500. The signs may require some refurbishment such as re-affixing lettering and replacing mounts, and estimates this cost to be approximately \$5,000 per sign.
		Client has advised that the "Spain" entry monument was refurbished in FY2017- 18 at a cost of \$38,013.19.
		Cost source: Ali Baudoin

High Desert Residential Owners Association, Inc. Funding Study Expense Item Summary - Continued

Category	Reserve Item Name Reserve Item Description					
	Monument High Desert Park Refurbishment	Component consists of one sign consisting of approximately 48 sq. ft. of stucco over block with metal lettering and artwork. Ali Baudoin, the artist who created similar signage throughout the community, has estimated the replacement cost at approximately \$7,500. The sign may require some refurbishment such as re-affixing lettering and replacing mounts, and				
		estimates this cost to be approximately \$5,000. Cost source: Ali Baudoin				
		Component consists of one sign consisting of approximately 48 sq. ft. of stucco over block with metal lettering and artwork.				
	Monument Highlands at High Desert Refurbishment	Ali Baudoin, the artist who created this sign, has estimated the replacement cost at approximately \$7,500. The sign may require some refurbishment such as reaffixing lettering and replacing mounts, and estimates this cost to be approximately \$5,000.				
		Client has advised that plants, irrigation lines and solar lighting were added to this signage in 2012.				
Signage		Cost source: Ali Baudoin				
	Monument Michial Emery -	Funding has been included for replacement of the Michial Emery Trailhead sign face and post on a 12-year cycle. This sign appeared to be in good condition at the time of our site visit.				
	Bear Canyon Trailhead Replacement	At client's request, we increased the remaining useful life of this component to 3 years in the 2016 reserve study update.				
		Cost source: AFI Database				
		Component consists of one sign consisting of approximately 48 sq. ft. of stucco over block with metal lettering and artwork.				
	Monument Mountain Highlands at High Desert Refurbishment	Ali Baudoin, the artist who created this sign, has estimated the replacement cost at approximately \$7,500. The sign may require some refurbishment such as reaffixing lettering and replacing mounts, and estimates this cost to be approximately \$5,000.				
		Client advised that plants, irrigation lines and solar lighting were added to this signage in 2012.				
		Cost source: Ali Baudoin				

High Desert Residential Owners Association, Inc. Funding Study Expense Item Summary - Continued

Category	Reserve Item Name	Reserve Item Description			
		Component consists of one sign consisting of approximately 48 sq. ft. of stucco over block with metal lettering and artwork.			
	Monument Overlook at High Desert Refurbishment	Ali Baudoin, the artist who created this sign, has estimated the replacement cost at approximately \$7,500. The sign may require some refurbishment such as reaffixing lettering and replacing mounts, and estimates this cost to be approximately \$5,000.			
		Cost source: Ali Baudoin			
	Monument Pinon Point Refurbishment	Component consists of one sign consisting of approximately48 sq. ft. of stucco over block with metal lettering and artwork. Refurbishment includes stucco repairs and painting, and metal lettering and artwork cleaning and minor repairs.			
		Cost source: National Construction Estimator			
	Monument Solterra Refurbishment	Component consists of 22 sq. ft. of stucco signage with tile inserts. This is a two-sided sign. Refurbishment consists of stucco repairs and painting, and cleaning tile surfaces, and repairs to tile surfaces. Tile chipping was noted during our site visit.			
		Cost source: National Construction Estimator			
Signage	Monument Sunset Ridge Refurbishment	Component consists of 22 sq. ft. of split-faced block wall with metal lettering on each side (two-sided sign). Refurbishment consists of block repairs and painting, and metal lettering cleaning and minor repairs.			
		Cost source: National Construction Estimator			
	Monument The Aerie Refurbishment	This sign is new, and consists of approximately 22 sq. ft. of split-faced block wall with metal lettering. Refurbishment consists of block repairs and painting, and metal lettering cleaning and minor repairs.			
		Cost source: National Construction Estimator			
		This refurbishment includes cleaning and minor repairs tothe stone face and lettering.			
	Monument The Canyons at High Desert Refurbishment	The paint on the sign-face lettering was in faded condition at the time of our September 5, 2017 site visit.			
		Client has advised that monument signage for all gated parcels will be maintained by the High Desert Residential Owners Association in accordance with the Association's "Gated Village Maintenance Policy."			
		Cost source: National Construction Estimator			

High Desert Residential Owners Association, Inc. Funding Study Expense Item Summary - Continued

Category	Reserve Item Name	Reserve Item Description				
		The monument consists of stacked-stone over painted stucco wall with metal lettering. Refurbishment includes minor stone tuckpointing and cleaning, stucco repairs and painting, and metal lettering cleaning.				
	Monument The Enclave at High Desert Refurbishment	At client's request, the remaining useful life of this component was increased to 5 years in the 2016 reserve study update. However, some metal leaching on the sign lettering was noted during our September 5, 2017 site visit, and we have therefore reset the remaining useful life to zero.				
		Client has advised that monument signage for all gated parcels will be maintained by the High Desert Residential Owners Association in accordance with the Association's "Gated Village Maintenance Policy."				
		Cost source: National Construction Estimator				
		This component consists of:				
		1 - double-sided stone sign with metal lettering				
Circago		Refurbishment includes cleaning and minor repairs on stone face and metal lettering.				
Signage	Monument The Legends at High Desert Refurbishment	At client's request, we increased the remaining useful life of this component to 7 years in the 2016 reserve study update.				
		Client has advised that monument signage for all gated parcels will be maintained by the High Desert Residential Owners Association in accordance with the Association's "Gated Village Maintenance Policy."				
		Cost source: National Construction Estimator				
		Refurbishment includes cleaning and minor repairs on stone surface and lettering.				
	Monument The Trillium at High Desert Refurbishment	Client has advised that monument signage for all gated parcels will be maintained by the High Desert Residential Owners Association in accordance with the Association's "Gated Village Maintenance Policy."				
		Cost source: National Construction Estimator				
	Monument Tierra Del Oso Refurbishment	Component consists of 22 sq. ft. of split-faced block wall with metal lettering (one-sided sign). Refurbishment consists of block repairs and painting, and metal lettering cleaning and minor repairs.				
		Cost source: National Construction Estimator				
		I				

High Desert Residential Owners Association, Inc. Funding Study Expense Item Summary - Continued

Category	Reserve Item Name	Reserve Item Description
		Component consists of one sign consisting of approximately 48 sq. ft. of stucco over block with metal lettering and artwork.
	Monument Trailhead at High Desert Refurbishment	Ali Baudoin, the artist who created this sign, has estimated the replacement cost at approximately \$7,500. The sign may require some refurbishment such as reaffixing lettering and replacing mounts, and estimates this cost to be approximately \$5,000.
		Cost source: Ali Baudoin
		Component consists of one sign consisting of approximately 48 sq. ft. of stucco over block with metal lettering and artwork.
	Monument West Highlands at High Desert Refurbishment	Ali Baudoin, the artist who created this sign, has estimated the replacement cost at approximately \$7,500. The sign may require some refurbishment such as reaffixing lettering and replacing mounts, and estimates this cost to be approximately \$5,000.
Signage		Cost source: Ali Baudoin
		Component consists of one sign consisting of approximately 48 sq. ft. of stucco over block with metal lettering and artwork. Refurbishment includes stucco repairs and painting, and cleaning of the metal lettering and artwork.
	Monument Wilderness At High Desert Refurbishment	Client advised that plants, irrigation lines and solar lighting were added to this signage in 2012.
		Cost source: National Construction Estimator
		Refurbishment consists of minor stone tuckpointing and cleaning of the stone surfaces.
	Monument Wilderness Canon Refurbishment	Client has advised that monument signage for all gated parcels will be maintained by the High Desert Residential Owners Association in accordance with the Association's "Gated Village Maintenance Policy."
		Cost source: National Construction Estimator

High Desert Residential Owners Association, Inc. Funding Study Expense Item Summary - Continued

Category	Reserve Item Name Reserve Item Description					
		Refurbishment consists of minor stone tuckpointing and cleaning of the stone surfaces.				
		The paint on the sign-face lettering was in faded condition at the time of our September 5, 2017 site visit.				
	Monument Wilderness Compound Refurbishment	Client has advised that 4,922.00 was spent in FY2017-18 for monument sign repairs.				
		Client has advised that monument signage for all gated parcels will be maintained by the High Desert Residential Owners Association in accordance with the Association's "Gated Village Maintenance Policy."				
		Cost source: National Construction Estimator				
		Component consists of one sign consisting of approximately 48 sq. ft. of stucco over block with metal lettering and artwork.				
Signage	Monument Wilderness Estates at High Desert Refurbishment	Ali Baudoin, the artist who created this sign, has estimated the replacement cost at approximately \$7,500. The sign may require some refurbishment such as reaffixing lettering and replacing mounts, and estimates this cost to be approximately \$5,000.				
		Cost source: Ali Baudoin				
	Monument Wilderness Village Refurbishment	Component consists of a wall of moss rock with metal lettering. This refurbishment includes cleaning and minor repairs to the stone wall and metal lettering.				
		Cost source: National Construction Estimator				
		Component consists of approximately 20 direction/location signs along the hiking trail:				
		20 - 20" x 25" metal sign kiosks				
	Signs Hiking Trail Replacement	Client advised that 16 park trail map faces were replaced in August 2013 at a total cost of \$1,712.00.				
		Cost source: Client				
		Cost source: AFI Database				

High Desert Residential Owners Association, Inc. Funding Study Expense Item Summary - Continued

Category	Reserve Item Name	Reserve Item Description					
		Client advised that there is a total of 35 pet waste stations within the communan average cost of \$500.					
Signage	Signs Pet Waste Stations Replacement	At client's request, we increased the useful life and remaining useful life of this component to 35 years in the 2016 reserve study update.					
		Cost source: Client					

Prepared by Great Boards, LLC High Desert Residential Owners Association, Inc. Reserve Study Expense Item Listing

Reserve Items	Unit Cost	No Units	Current Cost When New	Estimated Remaining Life	Expected Life When New	Fiscal Calendar Year	Estimated Future Cost		
	Asphalt & Concrete								
				0 Years		2021	\$ 2,451		
						2026	\$ 2,778		
Asphalt						2031	\$ 3,147		
Cracksealing & Repairs Michial	\$ 2,391 ea	1	\$ 2,391	5 Years	5 Years	2036	\$ 3,565		
Emery Trailhead				Jieais		2041	\$ 4,040		
						2046	\$ 4,577		
						2051	\$ 5,186		
				3 Years		2024	\$ 1,658		
						2029	\$ 1,878		
Asphalt					5 Years	2034	\$ 2,128		
Cracksealing &	\$ 1,500 ea 1	1	\$ 1,500	5 Years		2039	\$ 2,411		
Repairs Trail						2044	\$ 2,731		
						2049	\$ 3,095		
						2054	\$ 3,506		
Asphalt Resurfacing	\$ 26,998 ea	1	\$ 26,998	8 Years	30 Years	2029	\$ 33,802		
Michial Emery Trailhead	4 20,000 00.			30 Years		2059	\$ 71,504		
Asphalt	\$ 91,760 ea	1	\$ 91,760	13 Years	30 Years	2034	\$ 130,166		
Resurfacing Trail	ψ 91,700 c a	ı	ψ 91,700	30 Years	30 Tears	2064	\$ 275,347		
				3 Years		2024	\$ 3,342		
					5 Years	2029	\$ 3,786		
Asphalt						2034	\$ 4,290		
Sealcoating Michial	\$ 3,024 ea	1	\$ 3,024	5 Years		2039	\$ 4,860		
Emery Trailhead				o rears		2044	\$ 5,507		
						2049	\$ 6,239		
						2054	\$ 7,069		
				3 Years		2024	\$ 8,407		
Acabalt			\$ 7,608		5 Years	2029	\$ 9,525		
Asphalt Sealcoating Trail	\$ 0.12 / ft ² 63400 ft ²	63400 ft ²		5 Years		2034	\$ 10,792		
				O TOUIS		2039	\$ 12,228		
						2044	\$ 13,854		

High Desert Residential Owners Association, Inc. Reserve Study Expense Item Listing - Continued

Reserve Items	Unit Cost	No Units	Current Cost When New	Estimated Remaining Life	Expected Life When New	Fiscal Calendar Year	Estimated Future Cost
Asphalt Sealcoating Trail	\$ 0.12 / ft²	63400 ft²	\$ 7,608	5 Years	5 Years	2049 2054	\$ 15,697 \$ 17,784
- Coulous III Trail				8 Years		2029	\$ 7,512
Concrete	\$ 12.00 / ft²	500 ft²	\$ 6,000		10 Years	2039	\$ 9,643
Sidewalks Repairs	\$ 12.00 / IL	300 II	\$ 0,000	10 Years	10 Teals	2049	\$ 12,379
						2059	\$ 15,891
			Fences & Ga	ites			
Fence Metal Perimeter Desert Mountain Replacement	\$ 3,042 ea	1	\$ 3,042	30 Years	35 Years	2051	\$ 6,598
Fence Metal Perimeter Solterra Replacement	\$ 22.00 / If	26 If	\$ 572	30 Years	35 Years	2051	\$ 1,241
Fence Metal Perimeter The Canyons Replacement	\$ 22.00 / If	2965 lf	\$ 65,230	30 Years	35 Years	2051	\$ 141,474
Fence Metal Perimeter The Enclave Replacement	\$ 1,248 ea	1	\$ 1,248	30 Years	35 Years	2051	\$ 2,707
Fence Metal Perimeter The Legends Replacement	\$ 1,375 ea	1	\$ 1,375	30 Years	35 Years	2051	\$ 2,982
Fence Metal Perimeter The Trillium Replacement	\$ 8,224 ea	1	\$ 8,224	30 Years	35 Years	2051	\$ 17,837
Fence Metal Perimeter Tierra Del Oso Replacement	\$ 22.00 / If	1430 lf	\$ 31,460	30 Years	35 Years	2051	\$ 68,232

High Desert Residential Owners Association, Inc. Reserve Study Expense Item Listing - Continued

Reserve Items	Unit Cost	No Units	Current Cost When New	Estimated Remaining Life	Expected Life When New	Fiscal Calendar Year	Estimated Future Cost
Fence Metal Perimeter Tramway Replacement	\$ 0.00 / lf	120 lf	\$0	30 Years	35 Years	2051	\$0
Fence Metal Perimeter Wilderness Replacement	\$ 22.00 / If	160 lf	\$ 3,520	30 Years	35 Years	2051	\$ 7,634
Fence Metal Perimeter Wilderness Compound Replacement	\$ 2,790 ea	1	\$ 2,790	30 Years	35 Years	2051	\$ 6,050
Fence Metal Pipe Rail Replacement	\$ 26.00 / If	240 lf	\$ 6,240	8 Years 25 Years	25 Years	2029 2054	\$ 7,813 \$ 14,586
Fence Range Open Range Replacement Future	\$ 75,000 ea	1	\$ 75,000	11 Years 20 Years	20 Years	2032 2052	\$ 101,208 \$ 166,777
Gates Metal Access Replacement	\$ 12,096 ea	1	\$ 12,096	32 Years	35 Years	2053	\$ 27,578
Gates Metal Michial Emery Trailhead Replacement	\$ 47.20 / If	25 lf	\$ 1,180	32 Years	35 Years	2053	\$ 2,690
		Lan	dscaping & Ir	rigation			
Irrigation Backflow Preventers Replacement	\$ 1,500 ea	29	\$ 43,500	0 Years 15 Years	15 Years	2021 2036 2051	\$ 44,600 \$ 64,867 \$ 94,345
Irrigation Controllers Pinion Point Park Unfunded	\$ 0.00 ea	1	\$0	35 Years	35 Years	2056	\$0
Irrigation Controllers	\$ 2,500 ea	8	\$ 20,000	0 Years 10 Years	10 Years	2021 2031	\$ 20,506 \$ 26,323

High Desert Residential Owners Association, Inc. Reserve Study Expense Item Listing - Continued

Reserve Items	Unit Cost	No Units	Current Cost When New	Estimated Remaining Life	Expected Life When New	Fiscal Calendar Year	Estimated Future Cost
Irrigation	\$ 2,500 ea	8	\$ 20,000	10 Years	10 Years	2041	\$ 33,791
Controllers	φ 2,500 ea	0	φ 20,000	10 Teats	10 16415	2051	\$ 43,377
Irrigation Flow				0 Years		2021	\$ 4,614
Meters	\$ 1,500 ea	3	\$ 4,500	15 Years	15 Years	2036	\$ 6,710
Replacement				10 10013		2051	\$ 9,760
Letter Control				0 Years		2021	\$ 15,379
Irrigation Lateral Line Replacement	\$ 2.00 / If	7500 lf	\$ 15,000	15 Years	15 Years	2036	\$ 22,368
				15 Teals		2051	\$ 32,533
Irrigation Main Line	\$ 3.50 / If	30830 lf	\$ 107,905	15 Years	30 Years	2036	\$ 160,908
Replacement	ψ 5.50 / 11	30030 11	ψ 107,303	30 Years	30 Teals	2066	\$ 340,377
				3 Years		2024	\$ 1,243
						2029	\$ 1,409
Irrigation Spray		225				2034	\$ 1,596
Heads	\$ 5.00 ea		\$ 1,125	5 Years	5 Years	2039	\$ 1,808
Replacement				J Tears		2044	\$ 2,049
						2049	\$ 2,321
						2054	\$ 2,630
				3 Years	10 Years	2024	\$ 5,525
Irrigation System Common Area	\$ 5,000 ea	1	\$ 5,000			2034	\$ 7,093
Allowance	φ 0,000 ca			10 Years		2044	\$ 9,105
						2054	\$ 11,688
Irrigation System Pinion Point Park	\$ 8,250 ea	2	\$ 16,500	8 Years	30 Years	2029	\$ 20,658
Replacement	ψ 0,230 ca	_	Ψ 10,300	30 Years	30 10013	2059	\$ 43,700
				8 Years		2029	\$ 14,254
Irrigation Valve Boxes	\$ 45.00 ea	252	¢ 11 205		10 Years	2039	\$ 18,298
Replacement	ф 45.00 ea	253	\$ 11,385	10 Years	TO Tears	2049	\$ 23,489
						2059	\$ 30,153
				5 Years		2026	\$ 161,644
Irrigation Valves	\$ 550 ea	253	\$ 139,150		7 Years	2033	\$ 192,523
Replacement	ф ээл ө а			7 Years	r rears	2040	\$ 229,300
						2047	\$ 273,103

High Desert Residential Owners Association, Inc. Reserve Study Expense Item Listing - Continued

Reserve Items	Unit Cost	No Units	Current Cost When New	Estimated Remaining Life	Expected Life When New	Fiscal Calendar Year	Estimated Future Cost
Irrigation Valves	\$ 550 ea	253	\$ 139,150	7 Years	7 Years	2054	\$ 325,274
Irrigation Water				5 Years		2026	\$ 84,220
Meters	\$ 2,500 ea	29	\$ 72,500	20 Years	20 Years	2046	\$ 138,783
Replacement				20 16415		2066	\$ 228,695
				0 Years		2021	\$ 1,025
						2023	\$ 1,078
						2025	\$ 1,133
						2027	\$ 1,191
						2029	\$ 1,252
						2031	\$ 1,316
Landscape		1 \$1,0		2 Years	2 Years	2033	\$ 1,384
Decomposed	# 4 000		# 4 000			2035	\$ 1,454
Granite	\$ 1,000 ea		\$ 1,000			2037	\$ 1,529
Refurbishment						2039	\$ 1,607
						2041	\$ 1,690
						2043	\$ 1,776
						2045	\$ 1,867
						2047	\$ 1,963
						2049	\$ 2,063
						2051	\$ 2,169
				7 Years		2028	\$ 24,423
Landscaping Plant	¢ 20 000 aa	4	f 20 000		10 Vaara	2038	\$ 31,352
Material Replacement	\$ 20,000 ea	1	\$ 20,000	10 Years	10 Years	2048	\$ 40,246
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,						2058	\$ 51,663
				0 Years		2021	\$ 21,531
						2026	\$ 24,395
Landscaping Turf						2031	\$ 27,639
Pinion Point Park	\$ 21.00 / ft²	1000 ft²	\$ 21,000	E Voors	5 Years	2036	\$ 31,315
Replacement				5 Years		2041	\$ 35,480
						2046	\$ 40,199
						2051	\$ 45,546

High Desert Residential Owners Association, Inc. Reserve Study Expense Item Listing - Continued

Reserve Items	Unit Cost	No Units	Current Cost When New	Estimated Remaining Life	Expected Life When New	Fiscal Calendar Year	Estimated Future Cost					
			L'abta a									
			Lighting	437		0005	A. 2. 4.0.0					
		13		4 Years		2025	\$ 2,136					
Accent Lights	\$ 145 ea		\$ 1,885		10 Years	2035	\$ 2,742					
Replacement				10 Years		2045	\$ 3,519					
						2055	\$ 4,518					
Painting & Repairs												
				0 Years		2021	\$ 26,427					
						2028	\$ 31,475					
Metal Fences and Gates Painting	\$ 25,775 ea			7 Years		2035	\$ 37,488					
		1	\$ 25,775		7 Years	2042	\$ 44,649					
						2049	\$ 53,178					
						2056	\$ 63,337					
				1 Year		2022	\$ 2,281					
Ramada Chamisa	\$ 2,170 ea	1	\$ 2,170		25 Years	2047	\$ 4,259					
Park Refurbishment	·		·	25 Year		2072	\$ 7,952					
Ramada Pinon	\$ 1,682 ea	1	\$ 1,682	2 Years		2023	\$ 1,813					
Point Park					25 Years	2048	\$ 3,385					
Refurbishment	·			25 Years		2073	\$ 6,319					
				8 Years		2029	\$ 201,721					
Stucco Walls						2039	\$ 258,947					
Painting	\$ 0.60 / ft ²	268525 ft ²	\$ 161,115	10 Years	10 Years	2049	\$ 332,408					
						2059	\$ 426,710					
				8 Years		2029	\$ 13,447					
Stucco Walls						2039	\$ 17,262					
Repairs	\$ 2.00 / ft ²	5370 ft²	\$ 10,740	10 Years	10 Years	2049	\$ 22,158					
						2059	\$ 28,445					
							, ,					
		Park	Furniture & E	Elements								
		2		5 Years		2026	\$ 3,136					
Art Restoration	\$ 1,350 ea		\$ 2,700	20 Years	20 Years	2046	\$ 5,168					
				20 16013		2066	\$ 8,517					

High Desert Residential Owners Association, Inc. Reserve Study Expense Item Listing - Continued

Reserve Items	Unit Cost	No Units	Current Cost When New	Estimated Remaining Life	Expected Life When New	Fiscal Calendar Year	Estimated Future Cost
Park Furniture Chamisa Park Replacement	\$ 1,125 ea	1	\$ 1,125	30 Years	35 Years	2051	\$ 2,440
Park Furniture Medara Park Replacement	\$ 2,300 ea	1	\$ 2,300	30 Years	35 Years	2051	\$ 4,988
Park Furniture Pinion Point Park Replacement	\$ 800 ea	1	\$ 800	30 Years	35 Years	2051	\$ 1,735
Play Equipment				8 Years		2029	\$ 20,508
Pinion Point Park Replacement	\$ 16,380 ea	1	\$ 16,380	15 Years	15 Years	2044 2059	\$ 29,828 \$ 43,382
			0:				
			Signage	2 Years		2023	\$ 404
Monument Chaco				2 16015		2025	\$ 545
Ridge & Compound	\$ 375 ea	1	\$ 375	12 Years	12 Years	2047	\$ 736
Refurbishment				12 10010		2059	\$ 993
				2 Years		2023	\$ 404
Monument			\$ 375			2035	\$ 545
Chamisa Trail Refurbishment	\$ 375 ea	1		12 Years	12 Years	2047	\$ 736
Returbishment						2059	\$ 993
Monument Desert				6 Years		2027	\$ 5,955
Highlands at High Desert	\$ 5,000 ea	1	\$ 5,000		12 Years	2039	\$ 8,036
Refurbishment				12 Years		2051	\$ 10,844
Monument Desert				6 Years		2027	\$ 893
Mountain at High Desert	\$ 375 ea	2	\$ 750		12 Years	2039	\$ 1,205
Refurbishment				12 Years		2051	\$ 1,627
				2 Years		2023	\$ 404
Monument Desert	# 075	,	ф oze		40.7/	2035	\$ 545
Sky Refurbishment	\$ 375 ea	1	\$ 375	12 Years	12 Years	2047	\$ 736
						2059	\$ 993
Monument Desert	\$ 375 ea	1	\$ 375	2 Years	10 Years	2023	\$ 404

High Desert Residential Owners Association, Inc. Reserve Study Expense Item Listing - Continued

			Current	Estimated	Expected	Fiscal	Estimated	
Reserve Items	Unit Cost	No Units	Cost When New	Remaining Life	Life When New	Calendar Year	Future Cost	
Monument Desert						2033	\$ 519	
Song Refurbishment	\$ 375 ea	1	\$ 375	10 Years	10 Years	2043	\$ 666 \$ 855	
				6 Years		2053 2027	\$ 23,821	
Monument High				0 Teals		2027	\$ 23,621	
Desert	\$ 5,000 ea	4	\$ 20,000	10 Years	10 Years	2037	\$ 39,253	
Refurbishment				10 Teals		2047	\$ 50,389	
				3 Years		2024	\$ 5,525	
Monument High				o rears		2034	\$ 7,093	
Desert Park	\$ 5,000 ea	1	\$ 5,000	10 Years	10 Years	2044	\$ 9,105	
Refurbishment						2054	\$ 11,688	
Monument				6 Years		2027	\$ 5,955	
Highlands at High Desert Refurbishment	\$ 5,000 ea	1	\$ 5,000		12 Years	2039	\$ 8,036	
	·	·	, 2,323	12 Years		2051	\$ 10,844	
Monument Michial				8 Years		2029	\$ 470	
Emery - Bear Canyon Trailhead	\$ 375 ea	1	\$ 375	40.4	12 Years	2041	\$ 634	
Replacement				12 Years		2053	\$ 855	
Monument				6 Years		2027	\$ 5,955	
Mountain Highlands at High Desert	\$ 5,000 ea	1	\$ 5,000	,	12 Years	2039	\$ 8,036	
Refurbishment				12 Years		2051	\$ 10,844	
Monument				6 Years		2027	\$ 5,955	
Overlook at High	\$ 5,000 ea	1	\$ 5,000		12 Years	2039	\$ 8,036	
Desert Refurbishment				12 Years		2051	\$ 10,844	
				2 Years		2023	\$ 463	
Monument Pinon	# 400		A 400		40.1/	2035	\$ 625	
Point Refurbishment	\$ 430 ea	1	\$ 430	12 Years	12 Years	2047	\$ 844	
						2059	\$ 1,139	
				6 Years		2027	\$ 447	
Monument Solterra Refurbishment	\$ 375 ea	1	\$ 375	12 Vooro	12 Years	2039	\$ 603	
Neiuibisiilleilt				12 Years		2051	\$ 813	
Monument Sunset	\$ 375 ea	1	\$ 375	2 Years	12 Years	2023	\$ 404	

High Desert Residential Owners Association, Inc. Reserve Study Expense Item Listing - Continued

Reserve Items	Unit Cost	No Units	Current Cost When New	Estimated Remaining Life	Expected Life When New	Fiscal Calendar Year	Estimated Future Cost
Monument Sunset						2035	\$ 545
Ridge	\$ 375 ea	1	\$ 375	12 Years	12 Years	2047	\$ 736
Refurbishment						2059	\$ 993
Monument The		1	\$ 375	7 Years		2028	\$ 458
Aerie	\$ 375 ea			40.1/	12 Years	2040	\$ 618
Refurbishment				12 Years		2052	\$ 834
Monument The				9 Years		2030	\$ 481
Canyons at High Desert	\$ 375 ea	1	\$ 375		12 Years	2042	\$ 650
Refurbishment				12 Years		2054	\$ 877
M The				7 Years		2028	\$ 519
Monument The Enclave at High		1	\$ 425		40.14	2038	\$ 666
Desert	\$ 425 ea			10 Years	10 Years	2048	\$ 855
Refurbishment						2058	\$ 1,098
Manager Tha				2 Years		2023	\$ 463
Monument The Legends at High						2035	\$ 625
Desert	\$ 430 ea	1	\$ 430	12 Years	12 Years	2047	\$ 844
Refurbishment						2059	\$ 1,139
Monument The		1	\$ 430	0 Years		2021	\$ 441
Trillium at High	\$ 430 ea				15 Years	2036	\$ 641
Desert Refurbishment				15 Years		2051	\$ 933
				2 Years		2023	\$ 307
Monument Tierra						2035	\$ 415
Del Oso	\$ 285 ea	1	\$ 285	12 Years	12 Years	2047	\$ 559
Refurbishment						2059	\$ 755
Monument				6 Years		2027	\$ 5,955
Trailhead at High	\$ 5,000 ea	1	\$ 5,000		12 Years	2039	\$ 8,036
Desert Refurbishment	ψ 0,000 c a	'	, 5,500	12 Years		2051	\$ 10,844
Monument West				6 Years		2027	\$ 5,955
Highlands at High	¢ = 000 ==	4	\$ 5,000	UIGAIS	10 Vaans		
Desert	\$ 5,000 ea	1		12 Years	12 Years	2039	\$ 8,036
Refurbishment						2051	\$ 10,844

High Desert Residential Owners Association, Inc. Reserve Study Expense Item Listing - Continued

Reserve Items	Unit Cost	No Units	Current Cost When New	Estimated Remaining Life	Expected Life When New	Fiscal Calendar Year	Estimated Future Cost
Monument				6 Years		2027	\$ 512
Wilderness At High Desert	\$ 430 ea	1	\$ 430	12 Years	12 Years	2039	\$ 691
Refurbishment				12 Teals		2051	\$ 933
Monument				12 Years		2033	\$ 519
Wilderness Canon	\$ 375 ea	1	\$ 375	15 Years	15 Years	2048	\$ 755
Refurbishment				10 10013		2063	\$ 1,098
Monument				12 Years		2033	\$ 519
Wilderness Compound Refurbishment	\$ 375 ea	1	\$ 375	15 Years	15 Years	2048	\$ 755
				13 Teals		2063	\$ 1,098
Monument				4 Years		2025	\$ 5,665
Wilderness Estates	\$ 5,000 ea	1	\$ 5,000		10 Years	2035	\$ 7,272
at High Desert			ψ 5,000	10 Years	10 10013	2045	\$ 9,335
Refurbishment						2055	\$ 11,983
				2 Years		2023	\$ 404
Monument Wilderness Village	\$ 375 ea	1	\$ 375		12 Years	2035	\$ 545
Refurbishment	ψ 070 Ca	'	ΨΟΙΟ	12 Years	12 10013	2047	\$ 736
						2059	\$ 993
Ciana Hilding Tra-9				3 Years		2024	\$ 11,603
Signs Hiking Trail Replacement	\$ 525 ea	20	\$ 10,500	20 Years	20 Years	2044	\$ 19,120
rtopiacomont				20 16013		2064	\$ 31,508
Signs Pet Waste Stations Replacement	\$ 500 ea	35	\$ 17,500	30 Years	35 Years	2051	\$ 37,955

Missing table information is identical to the first printed information above.

Months Remaining in Fiscal Calendar Year 2021: 12

Expected annual inflation: 2.50% Interest earned on reserve funds: 0.20% Initial Reserve: \$ 775,180

High Desert Residential Owners Association, Inc. Funding Study Cash Flow Analysis

Fiscal	A 15	Annual	Salvag	Annual	Annual	Net Reserve	%	Fully
Calendar	Annual Dues	Interest	е	Expenses	Income	Funds	Funde	Funded
Year				<u> </u>	Tax		d	Balance
2021	\$ 43,056	\$ 1,590		\$ 136,974		\$ 682,852	115.5	\$ 591,324
2022	\$ 43,056	\$ 1,405		\$ 2,281		\$ 725,032	131.6	\$ 551,068
2023	\$ 43,056	\$ 1,490		\$ 6,550		\$ 763,028	117.4	\$ 650,053
2024	\$ 65,930	\$ 1,587		\$ 37,303		\$ 793,241	105.8	\$ 749,402
2025	\$ 65,930	\$ 1,647		\$ 8,934		\$ 851,884	103.6	\$ 822,630
2026	\$ 88,300	\$ 1,785		\$ 276,173		\$ 665,796	71.7%	\$ 929,210
2027	\$ 88,300	\$ 1,413		\$ 62,595		\$ 692,914	90.0%	\$ 770,062
2028	\$ 120,008	\$ 1,496		\$ 56,875		\$ 757,544	91.4%	\$ 828,879
2029	\$ 120,008	\$ 1,625		\$ 338,035		\$ 541,142	60.3%	\$ 897,902
2030	\$ 148,672	\$ 1,219		\$ 481		\$ 690,551	100.7	\$ 685,460
2031	\$ 148,672	\$ 1,517		\$ 58,425		\$ 782,316	95.8%	\$ 816,558
2032	\$ 150,182	\$ 1,702		\$ 101,208		\$ 832,992	93.1%	\$ 894,451
2033	\$ 150,182	\$ 1,804		\$ 195,463		\$ 789,515	84.6%	\$ 933,659
2034	\$ 155,701	\$ 1,722		\$ 163,157		\$ 783,780	89.0%	\$ 880,267
2035	\$ 155,701	\$ 1,710		\$ 53,348		\$ 887,844	103.0	\$ 861,913
2036	\$ 159,902	\$ 1,922		\$ 290,376		\$ 759,292	79.2%	\$ 958,883
2037	\$ 159,902	\$ 1,665		\$ 32,107		\$ 888,752	108.6	\$ 818,745
2038	\$ 163,678	\$ 1,928		\$ 32,018		\$ 1,022,340	108.4	\$ 943,236
2039	\$ 163,678	\$ 2,195		\$ 377,780		\$ 810,432	75.4%	\$ 1,074,423
2040	\$ 177,835	\$ 1,784		\$ 229,918		\$ 760,133	88.6%	\$ 857,966
2041	\$ 177,835	\$ 1,683		\$ 75,634		\$ 864,018	109.2	\$ 791,271
2042	\$ 183,620	\$ 1,896		\$ 45,299		\$ 1,004,236	113.5	\$ 884,801
2043	\$ 183,620	\$ 2,177		\$ 2,442		\$ 1,187,590	116.9	\$ 1,015,619
2044	\$ 185,620	\$ 2,545		\$ 91,299		\$ 1,284,457	107.3	\$ 1,197,602
2045	\$ 185,620	\$ 2,739		\$ 14,722		\$ 1,458,094	112.4	\$ 1,297,100
2046	\$ 190,224	\$ 3,091		\$ 188,727		\$ 1,462,682	98.7%	\$ 1,481,744
2047	\$ 190,224	\$ 3,100		\$ 324,505		\$ 1,331,501	89.0%	\$ 1,496,874
2048	\$ 202,619	\$ 2,849		\$ 45,995		\$ 1,490,974	108.2	\$ 1,377,503
2049	\$ 202,619	\$ 3,168		\$ 473,028		\$ 1,223,733	79.2%	\$ 1,545,104
2050	\$ 216,449	\$ 2,646				\$ 1,442,828	112.4	\$ 1,283,662
2051	\$ 216,449	\$ 3,084		\$ 604,156		\$ 1,058,204	70.3%	\$ 1,505,263
Totals :	\$ 4,546,650	\$ 62,183	\$0	\$ 4,325,810	\$ 0	,		

The cash distribution shown in this table applies to repair and replacement cash reserves only.

Basis of Funding Study


Cash reserves have been set to a minimum of \$ 0

High Desert Residential Owners Association, Inc. Funding Study Cash Flow by Fiscal Calendar Year - Continued

Study Life = 30 years Initial Reserve Funds = \$ 775,180.07 Final Reserve Value = \$ 1,058,204.39

Annual Payments Held Constant for 2 years

High Desert Residential Owners Association, Inc. Funding Study Cash Flow by Fiscal Calendar Year - Continued



Fiscal Calendar Years

High Desert Residential Owners Association, Inc. Reserve Dues Summary Projected Dues by Month and by Fiscal Calendar Year

Fiscal Calendar Year	Member Monthly Operations Payment	Member Monthly Reserve Payment	Member Total Monthly Payment	Member Total Annual Payment	Monthly Reserve Payment	Annual Reserve Payment
2021	NA	\$ 2.24	\$ 2.24	\$ 26.84	\$ 3,588	\$ 43,056
2022	NA	\$ 2.24	\$ 2.24	\$ 26.84	\$ 3,588	\$ 43,056
2023	NA	\$ 2.24	\$ 2.24	\$ 26.84	\$ 3,588	\$ 43,056
2024	NA	\$ 3.43	\$ 3.43	\$ 41.10	\$ 5,494	\$ 65,930
2025	NA	\$ 3.43	\$ 3.43	\$ 41.10	\$ 5,494	\$ 65,930
2026	NA	\$ 4.59	\$ 4.59	\$ 55.05	\$ 7,358	\$ 88,300
2027	NA	\$ 4.59	\$ 4.59	\$ 55.05	\$ 7,358	\$ 88,300
2028	NA	\$ 6.23	\$ 6.23	\$ 74.82	\$ 10,001	\$ 120,008
2029	NA	\$ 6.23	\$ 6.23	\$ 74.82	\$ 10,001	\$ 120,008
2030	NA	\$ 7.72	\$ 7.72	\$ 92.69	\$ 12,389	\$ 148,672
2031	NA	\$ 7.72	\$ 7.72	\$ 92.69	\$ 12,389	\$ 148,672
2032	NA	\$ 7.80	\$ 7.80	\$ 93.63	\$ 12,515	\$ 150,182
2033	NA	\$ 7.80	\$ 7.80	\$ 93.63	\$ 12,515	\$ 150,182
2034	NA	\$ 8.09	\$ 8.09	\$ 97.07	\$ 12,975	\$ 155,701
2035	NA	\$ 8.09	\$ 8.09	\$ 97.07	\$ 12,975	\$ 155,701
2036	NA	\$ 8.31	\$ 8.31	\$ 99.69	\$ 13,325	\$ 159,902
2037	NA	\$ 8.31	\$ 8.31	\$ 99.69	\$ 13,325	\$ 159,902
2038	NA	\$ 8.50	\$ 8.50	\$ 102.04	\$ 13,640	\$ 163,678
2039	NA	\$ 8.50	\$ 8.50	\$ 102.04	\$ 13,640	\$ 163,678
2040	NA	\$ 9.24	\$ 9.24	\$ 110.87	\$ 14,820	\$ 177,835
2041	NA	\$ 9.24	\$ 9.24	\$ 110.87	\$ 14,820	\$ 177,835
2042	NA	\$ 9.54	\$ 9.54	\$ 114.48	\$ 15,302	\$ 183,620
2043	NA	\$ 9.54	\$ 9.54	\$ 114.48	\$ 15,302	\$ 183,620
2044	NA	\$ 9.64	\$ 9.64	\$ 115.72	\$ 15,468	\$ 185,620
2045	NA	\$ 9.64	\$ 9.64	\$ 115.72	\$ 15,468	\$ 185,620
2046	NA	\$ 9.88	\$ 9.88	\$ 118.59	\$ 15,852	\$ 190,224
2047	NA	\$ 9.88	\$ 9.88	\$ 118.59	\$ 15,852	\$ 190,224
2048	NA	\$ 10.53	\$ 10.53	\$ 126.32	\$ 16,885	\$ 202,619
2049	NA	\$ 10.53	\$ 10.53	\$ 126.32	\$ 16,885	\$ 202,619
2050	NA	\$ 11.25	\$ 11.25	\$ 134.94	\$ 18,037	\$ 216,449
2051	NA	\$ 11.25	\$ 11.25	\$ 134.94	\$ 18,037	\$ 216,449

In the context of the Reserve Payment Summary, the "Annual Reserve Payment" corresponds with the "Annual Revenue" in the Cash Flow report.

High Desert Residential Owners Association, Inc. Funding Study Payment Summary by Fiscal Calendar Year - Continued

Number of Payment Months in Fiscal Calendar Year 2021: 12 Number of Years of Constant Payments: 2 No of Dues Paying Members: 1604

Prepared by Great Boards, LLC

High Desert Residential Owners Association, Inc. Funding Adjusted Revenue by Fiscal Calendar Year

Item Name	FY 2021	FY 2022	FY 2023	FY 2024	FY 2025	FY 2026	FY 2027	FY 2028	FY 2029	FY 2030	FY 2031	FY 2032	FY 2033	FY 2034	FY 2035
						Reserve C	ategory : Asp	halt & Concre	ete						
Asphalt Cracksealing & Repairs Michial Emery Trailhead	\$ 381	\$ 150	\$ 150	\$ 232	\$ 238	\$ 319	\$ 377	\$ 517	\$ 514	\$ 630	\$ 630	\$ 714	\$ 715	\$ 716	\$ 713
Asphalt Cracksealing & Repairs Trail	\$ 64	\$ 112	\$ 112	\$ 173	\$ 161	\$ 216	\$ 225	\$ 309	\$ 307	\$ 426	\$ 426	\$ 425	\$ 426	\$ 426	\$ 482
Asphalt Resurfacing Michial Emery Trailhead	\$ 579	\$ 1,006	\$ 1,012	\$ 1,563	\$ 1,600	\$ 2,150	\$ 2,240	\$ 3,076	\$ 3,056	\$ 2,327	\$ 2,327	\$ 2,326	\$ 2,328	\$ 2,331	\$ 2,321
Asphalt Resurfacing Trail	\$ 1,426	\$ 2,479	\$ 2,494	\$ 3,849	\$ 3,941	\$ 5,296	\$ 5,519	\$ 7,577	\$ 7,529	\$ 9,225	\$ 9,224	\$ 9,219	\$ 9,229	\$ 9,240	\$ 8,939
Asphalt Sealcoating Michial Emery Trailhead	\$ 129	\$ 225	\$ 226	\$ 349	\$ 324	\$ 436	\$ 454	\$ 623	\$ 619	\$ 859	\$ 859	\$ 859	\$ 860	\$ 861	\$ 971
Asphalt Sealcoating Trail	\$ 326	\$ 566	\$ 570	\$ 879	\$ 815	\$ 1,095	\$ 1,141	\$ 1,567	\$ 1,557	\$ 2,161	\$ 2,161	\$ 2,160	\$ 2,162	\$ 2,165	\$ 2,443
Concrete Sidewalks Repairs	\$ 129	\$ 224	\$ 225	\$ 347	\$ 355	\$ 478	\$ 498	\$ 683	\$ 679	\$ 961	\$ 961	\$ 960	\$ 961	\$ 962	\$ 959
Asphalt & Concrete Subtotal :	\$ 3,034	\$ 4,762	\$ 4,789	\$ 7,392	\$ 7,434	\$ 9,990	\$ 10,454	\$ 14,352	\$ 14,261	\$ 16,589	\$ 16,588	\$ 16,663	\$ 16,681	\$ 16,701	\$ 16,828
						Reserve	Category : F	ences & Gate	5						
Irrigation Backflow Preventers Replacement	\$ 6,929	\$ 1,152	\$ 1,159	\$ 1,788	\$ 1,831	\$ 2,461	\$ 2,564	\$ 3,520	\$ 3,498	\$ 4,286	\$ 4,286	\$ 4,283	\$ 4,288	\$ 4,293	\$ 4,276
Irrigation Controllers Pinion Point Park Unfunded															
Irrigation Controllers Replacement	\$ 3,186	\$ 705	\$ 709	\$ 1,094	\$ 1,120	\$ 1,505	\$ 1,569	\$ 2,154	\$ 2,140	\$ 2,622	\$ 2,622	\$ 3,364	\$ 3,368	\$ 3,372	\$ 3,358
Irrigation Flow Meters Replacement	\$ 717	\$ 119	\$ 120	\$ 185	\$ 190	\$ 255	\$ 265	\$ 364	\$ 362	\$ 444	\$ 444	\$ 443	\$ 444	\$ 444	\$ 443
Irrigation Lateral Line Replacement	\$ 2,389	\$ 397	\$ 400	\$ 617	\$ 631	\$ 849	\$ 884	\$ 1,214	\$ 1,206	\$ 1,478	\$ 1,478	\$ 1,477	\$ 1,479	\$ 1,480	\$ 1,474
Irrigation Main Line Replacement	\$ 1,539	\$ 2,676	\$ 2,692	\$ 4,155	\$ 4,254	\$ 5,717	\$ 5,958	\$ 8,180	\$ 8,128	\$ 9,958	\$ 9,958	\$ 9,952	\$ 9,962	\$ 9,975	\$ 9,934
Irrigation Spray Heads Replacement	\$ 48	\$ 84	\$ 84	\$ 130	\$ 120	\$ 162	\$ 169	\$ 231	\$ 230	\$ 320	\$ 320	\$ 320	\$ 320	\$ 320	\$ 361

Prepared by Great Boards, LLC

High Desert Residential Owners Association, Inc. Funding Adjusted Revenue by Fiscal Calendar Year - Continued

Item Name	FY 2021	FY 2022	FY 2023	FY 2024	FY 2025	FY 2026	FY 2027	FY 2028	FY 2029	FY 2030	FY 2031	FY 2032	FY 2033	FY 2034	FY 2035
Irrigation System Common Area Allowance	\$ 214	\$ 372	\$ 374	\$ 578	\$ 302	\$ 406	\$ 423	\$ 580	\$ 576	\$ 706	\$ 706	\$ 706	\$ 707	\$ 707	\$ 904
Irrigation System Pinion Point Park Replacement	\$ 354	\$ 615	\$ 619	\$ 955	\$ 978	\$ 1,314	\$ 1,369	\$ 1,880	\$ 1,868	\$ 1,423	\$ 1,423	\$ 1,422	\$ 1,423	\$ 1,425	\$ 1,419
Irrigation Valve Boxes Replacement	\$ 244	\$ 424	\$ 427	\$ 659	\$ 675	\$ 907	\$ 945	\$ 1,297	\$ 1,289	\$ 1,823	\$ 1,823	\$ 1,822	\$ 1,824	\$ 1,826	\$ 1,819
Irrigation Valves Replacement	\$ 4,165	\$ 7,241	\$ 7,285	\$ 11,244	\$ 11,511	\$ 15,470	\$ 16,440	\$ 22,571	\$ 22,428	\$ 27,479	\$ 27,478	\$ 27,461	\$ 27,491	\$ 32,784	\$ 32,650
Irrigation Water Meters Replacement	\$ 2,170	\$ 3,773	\$ 3,796	\$ 5,858	\$ 5,997	\$ 8,060	\$ 4,094	\$ 5,621	\$ 5,586	\$ 6,843	\$ 6,843	\$ 6,839	\$ 6,846	\$ 6,855	\$ 6,827
Landscape Decomposed Granite Refurbishment	\$ 159	\$ 145	\$ 146	\$ 237	\$ 243	\$ 343	\$ 358	\$ 516	\$ 513	\$ 661	\$ 661	\$ 694	\$ 694	\$ 732	\$ 729
Landscaping Plant Material Replacement	\$ 471	\$ 819	\$ 824	\$ 1,272	\$ 1,302	\$ 1,750	\$ 1,823	\$ 2,503	\$ 2,549	\$ 3,123	\$ 3,123	\$ 3,121	\$ 3,124	\$ 3,128	\$ 3,115
Landscaping Turf Pinion Point Park Replacement	\$ 3,345	\$ 1,313	\$ 1,321	\$ 2,038	\$ 2,087	\$ 2,804	\$ 3,311	\$ 4,546	\$ 4,517	\$ 5,534	\$ 5,534	\$ 6,266	\$ 6,273	\$ 6,281	\$ 6,255
Landscaping & Irrigation Subtotal :	\$ 25,930	\$ 19,835	\$ 19,956	\$ 30,810	\$ 31,241	\$ 42,003	\$ 40,172	\$ 55,177	\$ 54,890	\$ 66,700	\$ 66,699	\$ 68,170	\$ 68,243	\$ 73,622	\$ 73,564
						Reserve Cate	aorv : I ands	caping & Irrig	ation						
Accent Lights Replacement	\$ 66	\$ 115	\$ 116	\$ 178	\$ 183	\$ 157	\$ 163	\$ 224	\$ 223	\$ 273	\$ 273	\$ 272	\$ 273	\$ 273	\$ 272
						Poss	rve Category	ı : Liahtina					ı		
Metal Fences and Gates Painting	\$ 4,106	\$ 1,207	\$ 1,215	\$ 1,875	\$ 1,919	\$ 2,579	\$ 2,688	\$ 3,690	\$ 4,367	\$ 5,350	\$ 5,350	\$ 5,347	\$ 5,353	\$ 5,359	\$ 5,338
Ramada Chamisa Park Refurbishment	\$ 177	\$ 308	\$ 45	\$ 70	\$ 71	\$ 96	\$ 100	\$ 137	\$ 136	\$ 167	\$ 167	\$ 167	\$ 167	\$ 167	\$ 167
Ramada Pinon Point Park Refurbishment	\$ 94	\$ 163	\$ 164	\$ 55	\$ 57	\$ 76	\$ 79	\$ 109	\$ 108	\$ 133	\$ 133	\$ 133	\$ 133	\$ 133	\$ 132
Stucco Walls Painting	\$ 3,454	\$ 6,006	\$ 6,043	\$ 9,326	\$ 9,548	\$ 12,832	\$ 13,371	\$ 18,357	\$ 18,241	\$ 25,795	\$ 25,793	\$ 25,778	\$ 25,806	\$ 25,839	\$ 25,733
Stucco Walls Repairs	\$ 230	\$ 400	\$ 403	\$ 622	\$ 637	\$ 855	\$ 891	\$ 1,224	\$ 1,216	\$ 1,719	\$ 1,719	\$ 1,718	\$ 1,720	\$ 1,722	\$ 1,715
Painting & Repairs Subtotal	\$ 8,061	\$ 8,084	\$ 7,870	\$ 11,948	\$ 12,232	\$ 16,438	\$ 17,129	\$ 23,517	\$ 24,068	\$ 33,164	\$ 33,162	\$ 33,143	\$ 33,179	\$ 33,220	\$ 33,085

Prepared by Great Boards, LLC

High Desert Residential Owners Association, Inc. Funding Adjusted Revenue by Fiscal Calendar Year - Continued

Item Name	FY 2021	FY 2022	FY 2023	FY 2024	FY 2025	FY 2026	FY 2027	FY 2028	FY 2029	FY 2030	FY 2031	FY 2032	FY 2033	FY 2034	FY 2035
						Reserve C	ategory : Pai	nting & Repa	irs						
Art Restoration	\$ 81	\$ 141	\$ 141	\$ 218	\$ 223	\$ 300	\$ 152	\$ 209	\$ 208	\$ 255	\$ 255	\$ 254	\$ 255	\$ 255	\$ 254
Park Furniture Chamisa Park Replacement	\$ 12	\$ 21	\$ 21	\$ 32	\$ 33	\$ 44	\$ 46	\$ 63	\$ 62	\$ 76	\$ 76	\$ 76	\$ 76	\$ 77	\$ 76
Park Furniture Medara Park Replacement	\$ 24	\$ 42	\$ 42	\$ 65	\$ 67	\$ 90	\$ 94	\$ 129	\$ 128	\$ 157	\$ 157	\$ 157	\$ 157	\$ 157	\$ 157
Park Furniture Pinion Point Park Replacement	\$8	\$ 15	\$ 15	\$ 23	\$ 23	\$ 31	\$ 33	\$ 45	\$ 44	\$ 54	\$ 54	\$ 54	\$ 54	\$ 54	\$ 54
Play Equipment Pinion Point Park Replacement	\$ 351	\$ 610	\$ 614	\$ 948	\$ 970	\$ 1,304	\$ 1,359	\$ 1,866	\$ 1,854	\$ 1,971	\$ 1,971	\$ 1,970	\$ 1,972	\$ 1,974	\$ 1,966
Park Furniture & Elements Subtotal :	\$ 476	\$ 829	\$ 833	\$ 1,286	\$ 1,316	\$ 1,769	\$ 1,684	\$ 2,312	\$ 2,296	\$ 2,513	\$ 2,513	\$ 2,511	\$ 2,514	\$ 2,517	\$ 2,507
					R	eserve Categ	gory : Park Fu	ırniture & Ele	ments						
Monument Chaco Ridge & Compound Refurbishment	\$ 21	\$ 36	\$ 36	\$ 19	\$ 19	\$ 26	\$ 27	\$ 37	\$ 37	\$ 45	\$ 45	\$ 45	\$ 45	\$ 45	\$ 45
Monument Chamisa Trail Refurbishment	\$ 21	\$ 36	\$ 36	\$ 19	\$ 19	\$ 26	\$ 27	\$ 37	\$ 37	\$ 45	\$ 45	\$ 45	\$ 45	\$ 45	\$ 45
Monument Desert Highlands at High Desert Refurbishment	\$ 131	\$ 228	\$ 230	\$ 355	\$ 363	\$ 488	\$ 509	\$ 547	\$ 544	\$ 666	\$ 666	\$ 666	\$ 666	\$ 667	\$ 664
Monument Desert Mountain at High Desert Refurbishment	\$ 20	\$ 34	\$ 35	\$ 53	\$ 55	\$ 73	\$ 76	\$ 82	\$ 81	\$ 100	\$ 100	\$ 100	\$ 100	\$ 100	\$ 99
Monument Desert Sky Refurbishment	\$ 21	\$ 36	\$ 36	\$ 19	\$ 19	\$ 26	\$ 27	\$ 37	\$ 37	\$ 45	\$ 45	\$ 45	\$ 45	\$ 45	\$ 45
Monument Desert Song Refurbishment	\$ 21	\$ 36	\$ 36	\$ 21	\$ 22	\$ 29	\$ 31	\$ 42	\$ 42	\$ 51	\$ 51	\$ 51	\$ 51	\$ 67	\$ 66
Monument High Desert Refurbishment	\$ 525	\$ 914	\$ 919	\$ 1,419	\$ 1,452	\$ 1,952	\$ 2,034	\$ 2,502	\$ 2,486	\$ 3,046	\$ 3,046	\$ 3,044	\$ 3,048	\$ 3,052	\$ 3,039
Monument High Desert Park Refurbishment	\$ 214	\$ 372	\$ 374	\$ 578	\$ 302	\$ 406	\$ 423	\$ 580	\$ 576	\$ 706	\$ 706	\$ 706	\$ 707	\$ 707	\$ 904

Prepared by Great Boards, LLC

High Desert Residential Owners Association, Inc. Funding Adjusted Revenue by Fiscal Calendar Year - Continued

Item Name	FY 2021	FY 2022	FY 2023	FY 2024	FY 2025	FY 2026	FY 2027	FY 2028	FY 2029	FY 2030	FY 2031	FY 2032	FY 2033	FY 2034	FY 2035
Monument Highlands at High Desert Refurbishment	\$ 131	\$ 228	\$ 230	\$ 355	\$ 363	\$ 488	\$ 509	\$ <i>547</i>	\$ 544	\$ 666	\$ 666	\$ 666	\$ 666	\$ 667	\$ 664
Monument Michial Emery - Bear Canyon Trailhead Replacement	\$8	\$ 14	\$ 14	\$ 22	\$ 22	\$ 30	\$ 31	\$ 43	\$ 43	\$ 52	\$ 52	\$ 52	\$ 52	\$ 52	\$ 52
Monument Mountain Highlands at High Desert Refurbishment	\$ 131	\$ 228	\$ 230	\$ 355	\$ 363	\$ 488	\$ 509	\$ 547	\$ 544	\$ 666	\$ 666	\$ 666	\$ 666	\$ 667	\$ 664
Monument Overlook at High Desert Refurbishment	\$ 131	\$ 228	\$ 230	\$ 355	\$ 363	\$ 488	\$ 509	\$ 547	\$ 544	\$ 666	\$ 666	\$ 666	\$ 666	\$ 667	\$ 664
Monument Pinon Point Refurbishment	\$ 24	\$ 42	\$ 42	\$ 21	\$ 22	\$ 29	\$ 31	\$ 42	\$ 42	\$ 51	\$ 51	\$ 51	\$ 51	\$ 51	\$ 51
Monument Solterra Refurbishment	\$ 10	\$ 17	\$ 17	\$ 26	\$ 27	\$ 36	\$ 38	\$ 41	\$ 41	\$ 50	\$ 50	\$ 50	\$ 50	\$ 50	\$ 50
Monument Sunset Ridge Refurbishment	\$ 21	\$ 36	\$ 36	\$ 19	\$ 19	\$ 26	\$ 27	\$ 37	\$ 37	\$ 45	\$ 45	\$ 45	\$ 45	\$ 45	\$ 45
Monument The Aerie Refurbishment	\$ 9	\$ 15	\$ 16	\$ 24	\$ 24	\$ 33	\$ 34	\$ 47	\$ 42	\$ 51	\$ 51	\$ 51	\$ 51	\$ 51	\$ 51
Monument The Canyons at High Desert Refurbishment	\$ 7	\$ 13	\$ 13	\$ 20	\$ 21	\$ 28	<i>\$ 29</i>	\$ 40	\$ 39	\$ 48	\$ 53	\$ 53	\$ 53	\$ 53	\$ 53
Monument The Enclave at High Desert Refurbishment	\$ 10	\$ 17	\$ 17	\$ 27	\$ 28	\$ 37	\$ 39	\$ 53	\$ 54	\$ 66	\$ 66	\$ 66	\$ 66	\$ 67	\$ 66
Monument The Legends at High Desert Refurbishment	\$ 24	\$ 42	\$ 42	\$ 21	\$ 22	\$ 29	\$ 31	\$ 42	\$ 42	\$ 51	\$ 51	\$ 51	\$ 51	\$ 51	\$ 51
Monument The Trillium at High Desert Refurbishment	\$ 68	\$ 11	\$ 11	\$ 18	\$ 18	\$ 24	\$ 25	\$ 35	\$ 34	\$ 42	\$ 42	\$ 42	\$ 42	\$ 42	\$ 42
Monument Tierra Del Oso Refurbishment	\$ 16	\$ 28	\$ 28	\$ 14	\$ 15	\$ 20	\$ 20	\$ 28	\$ 28	\$ 34	\$ 34	\$ 34	\$ 34	\$ 34	\$ 34
Monument Trailhead at High Desert Refurbishment	\$ 131	\$ 228	\$ 230	\$ 355	\$ 363	\$ 488	\$ 509	\$ 547	\$ 544	\$ 666	\$ 666	\$ 666	\$ 666	\$ 667	\$ 664

Prepared by Great Boards, LLC

High Desert Residential Owners Association, Inc. Funding Adjusted Revenue by Fiscal Calendar Year - Continued

Item Name	FY 2021	FY 2022	FY 2023	FY 2024	FY 2025	FY 2026	FY 2027	FY 2028	FY 2029	FY 2030	FY 2031	FY 2032	FY 2033	FY 2034	FY 2035
Monument West Highlands at High Desert Refurbishment	\$ 131	\$ 228	\$ 230	\$ 355	\$ 363	\$ 488	\$ 509	\$ 547	\$ 544	\$ 666	\$ 666	\$ 666	\$ 666	\$ 667	\$ 664
Monument Wilderness At High Desert Refurbishment	\$ 11	\$ 20	\$ 20	\$ 31	\$ 31	\$ 42	\$ 44	\$ 47	\$ 47	\$ 57	\$ 57	\$ 57	\$ 57	\$ 57	\$ 57
Monument Wilderness Canon Refurbishment	\$ 6	\$ 11	\$ 11	\$ 16	\$ 17	\$ 23	\$ 23	\$ 32	\$ 32	\$ 39	\$ 39	\$ 39	\$ 39	\$ 50	\$ 50
Monument Wilderness Compound Refurbishment	\$ 6	\$ 11	\$ 11	\$ 16	\$ 17	\$ 23	\$ 23	\$ 32	\$ 32	\$ 39	\$ 39	\$ 39	\$ 39	\$ 50	\$ 50
Monument Wilderness Estates at High Desert Refurbishment	\$ 175	\$ 305	\$ 307	\$ 473	\$ 484	\$ 416	\$ 433	\$ 595	\$ 591	\$ 724	\$ 724	\$ 724	\$ 725	\$ 726	\$ 723
Monument Wilderness Village Refurbishment	\$ 21	\$ 36	\$ 36	\$ 19	\$ 19	\$ 26	\$ 27	\$ 37	\$ 37	\$ 45	\$ 45	\$ 45	\$ 45	\$ 45	\$ 45
Signs Hiking Trail Replacement	\$ 449	\$ 781	\$ 786	\$ 1,213	\$ 403	\$ 541	\$ 564	\$ 774	\$ 769	\$ 943	\$ 943	\$ 942	\$ 943	\$ 944	\$ 940
Signs Pet Waste Stations Replacement	\$ 185	\$ 321	\$ 323	\$ 498	\$ 510	\$ 686	\$ 714	\$ 981	\$ 975	\$ 1,194	\$ 1,194	\$ 1,193	\$ 1,195	\$ 1,196	\$ 1,191
Signage Subtotal :	\$ 2,679	\$ 4,552	\$ 4,582	\$ 6,736	\$ 5,765	\$ 7,515	\$ 7,832	\$ 9,505	\$ 9,445	\$ 11,565	\$ 11,570	\$ 11,566	\$ 11,575	\$ 11,627	\$ 11,778
						Rese	rve Category	: Sianaae							
Fence Metal Perimeter Desert Mountain Replacement	\$ 32	\$ 56	\$ 56	\$ 86	\$ 89	\$ 119	\$ 124	\$ 170	\$ 169	\$ 207	\$ 207	\$ 207	\$ 207	\$ 208	\$ 207
Fence Metal Perimeter Solterra Replacement	\$ 6	\$ 11	\$ 11	\$ 16	\$ 17	\$ 23	\$ 23	\$ 32	\$ 32	\$ 39	\$ 39	\$ 39	\$ 39	\$ 39	\$ 39
Fence Metal Perimeter The Canyons Replacement	\$ 688	\$ 1,196	\$ 1,203	\$ 1,857	\$ 1,901	\$ 2,555	\$ 2,663	\$ 3,656	\$ 3,633	\$ 4,451	\$ 4,451	\$ 4,448	\$ 4,453	\$ 4,458	\$ 4,440
Fence Metal Perimeter The Enclave Replacement	\$ 13	\$ 23	\$ 23	\$ 36	\$ 37	\$ 49	\$ 51	\$ 70	\$ 70	\$ 86	\$ 86	\$ 85	\$ 86	\$ 86	\$ 85
Fence Metal Perimeter The Legends Replacement	\$ 14	\$ 25	\$ 25	\$ 39	\$ 40	\$ 54	\$ 56	\$ 77	\$ 76	\$ 94	\$ 94	\$ 94	\$ 94	\$ 94	\$ 93
Fence Metal Perimeter The Trillium Replacement	\$ 87	\$ 151	\$ 152	\$ 234	\$ 240	\$ 322	\$ 336	\$ 461	\$ 458	\$ 561	\$ 561	\$ 561	\$ 562	\$ 562	\$ 560

Adjusted Revenue includes earned interest, tax adjustments, and salvage.

Prepared by Great Boards, LLC

High Desert Residential Owners Association, Inc. Funding Adjusted Revenue by Fiscal Calendar Year - Continued

Item Name	FY 2021	FY 2022	FY 2023	FY 2024	FY 2025	FY 2026	FY 2027	FY 2028	FY 2029	FY 2030	FY 2031	FY 2032	FY 2033	FY 2034	FY 2035
Fence Metal Perimeter Tierra Del Oso Replacement	\$ 332	\$ 577	\$ 580	\$ 896	\$ 917	\$ 1,233	\$ 1,285	\$ 1,764	\$ 1,752	\$ 2,147	\$ 2,147	\$ 2,146	\$ 2,148	\$ 2,151	\$ 2,142
Fence Metal Perimeter Tramway Replacement															
Fence Metal Perimeter Wilderness Replacement	\$ 37	\$ 65	\$ 65	\$ 100	\$ 103	\$ 138	\$ 144	\$ 198	\$ 196	\$ 240	\$ 240	\$ 240	\$ 241	\$ 241	\$ 240
Fence Metal Perimeter Wilderness Compound Replacement	\$ 29	\$ 51	\$ 51	\$ 79	\$ 81	\$ 109	\$ 114	\$ 156	\$ 155	\$ 190	\$ 190	\$ 190	\$ 190	\$ 190	\$ 190
Fence Metal Pipe Rail Replacement	\$ 134	\$ 233	\$ 234	\$ 361	\$ 370	\$ 497	\$ 518	\$ 711	\$ 706	\$ 572	\$ 572	\$ 572	\$ 573	\$ 573	\$ 571
Fence Range Open Range Replacement Future	\$ 1,296	\$ 2,253	\$ 2,267	\$ 3,499	\$ 3,582	\$ 4,814	\$ 5,016	\$ 6,887	\$ 6,844	\$ 8,385	\$ 8,384	\$ 8,379	\$ 8,227	\$ 8,238	\$ 8,204
Gates Metal Access Replacement	\$ 126	\$ 218	\$ 220	\$ 339	\$ 347	\$ 467	\$ 486	\$ 668	\$ 664	\$ 813	\$ 813	\$ 812	\$ 813	\$ 814	\$ 811
Gates Metal Michial Emery Trailhead Replacement	\$ 12	\$ 21	\$ 21	\$ 33	\$ 34	\$ 46	\$ 48	<i>\$ 65</i>	<i>\$ 65</i>	<i>\$ 79</i>	<i>\$ 79</i>	\$ 79	\$ 80	\$ 80	\$ 79
Fences & Gates Subtotal :	\$ 2,806	\$ 4,880	\$ 4,908	\$ 7,575	\$ 7,758	\$ 10,426	\$ 10,864	\$ 14,915	\$ 14,820	\$ 17,864	\$ 17,863	\$ 17,852	\$ 17,713	\$ 17,734	\$ 17,661
Total Revenue :	\$ 43,056	\$ 43,056	\$ 43,056	\$ 65,930	\$ 65,930	\$ 88,300	\$ 88,300	\$ 120,008	\$ 120,008	\$ 148,672	\$ 148,672	\$ 150,182	\$ 150,182	\$ 155,701	\$ 155,701

Prepared by Great Boards, LLC

High Desert Residential Owners Association, Inc. Funding Adjusted Revenue by Fiscal Calendar Year - Continued

Item Name	FY 2036	FY 2037	FY 2038	FY 2039	FY 2040	FY 2041	FY 2042	FY 2043	FY 2044	FY 2045	FY 2046	FY 2047	FY 2048	FY 2049
				<u>'</u>	Reserv	e Category : /	Asphalt & Cor	ocrete		'	<u> </u>		'	·
Asphalt Cracksealing & Repairs Michial Emery Trailhead	\$ 725	\$ 796	\$ 811	\$ 806	\$ 822	\$ 794	\$ 918	\$ 912	\$ 922	\$ 909	\$ 929	\$ 1,021	\$ 1,040	\$ 1,033
Asphalt Cracksealing & Repairs Trail	\$ 490	\$ 475	\$ 484	\$ 481	\$ 556	\$ 537	\$ 548	\$ 545	\$ 550	\$ 614	\$ 628	\$ 610	\$ 621	\$ 617
Asphalt Resurfacing Michial Emery Trailhead	\$ 2,362	\$ 2,291	\$ 2,332	\$ 2,319	\$ 2,366	\$ 2,284	\$ 2,332	\$ 2,316	\$ 2,341	\$ 2,307	\$ 2,359	\$ 2,289	\$ 2,330	\$ 2,315
Asphalt Resurfacing Trail	\$ 9,094	\$ 8,821	\$ 8,979	\$ 8,929	\$ 9,110	\$ 8,795	\$ 8,978	\$ 8,918	\$ 9,012	\$ 8,884	\$ 9,084	\$ 8,812	\$ 8,972	\$ 8,914
Asphalt Sealcoating Michial Emery Trailhead	\$ 987	\$ 958	\$ 975	\$ 970	\$ 1,121	\$ 1,082	\$ 1,105	\$ 1,097	\$ 1,109	\$ 1,239	\$ 1,267	\$ 1,229	\$ 1,251	\$ 1,243
Asphalt Sealcoating Trail	\$ 2,485	\$ 2,411	\$ 2,454	\$ 2,440	\$ 2,820	\$ 2,723	\$ 2,779	\$ 2,761	\$ 2,790	\$ 3,116	\$ 3,186	\$ 3,091	\$ 3,147	\$ 3,127
Concrete Sidewalks Repairs	\$ 975	\$ 946	\$ 963	\$ 958	\$ 1,254	\$ 1,211	\$ 1,236	\$ 1,228	\$ 1,241	\$ 1,223	\$ 1,251	\$ 1,213	\$ 1,235	\$ 1,227
Asphalt & Concrete Subtotal :	\$ 17,118	\$ 16,698	\$ 16,998	\$ 16,903	\$ 18,049	\$ 17,426	\$ 17,896	\$ 17,777	\$ 17,965	\$ 18,292	\$ 18,704	\$ 18,265	\$ 18,596	\$ 18,476
					Rese	erve Category	: Fences & Ga	ates						
Irrigation Backflow Preventers Replacement	\$ 4,350	\$ 6,137	\$ 6,247	\$ 6,212	\$ 6,338	\$ 6,118	\$ 6,246	\$ 6,204	\$ 6,270	\$ 6,180	\$ 6,320	\$ 6,131	\$ 6,242	\$ 6,202
Irrigation Controllers Pinion Point Park Unfunded														
Irrigation Controllers Replacement	\$ 3,417	\$ 3,314	\$ 3,373	\$ 3,355	\$ 3,423	\$ 3,304	\$ 4,330	\$ 4,301	\$ 4,346	\$ 4,284	\$ 4,381	\$ 4,250	\$ 4,327	\$ 4,299
Irrigation Flow Meters Replacement	\$ 450	\$ 635	\$ 646	\$ 643	\$ 656	\$ 633	\$ 646	\$ 642	\$ 649	\$ 639	\$ 654	\$ 634	\$ 646	\$ 642
Irrigation Lateral Line Replacement	\$ 1,500	\$ 2,117	\$ 2,154	\$ 2,143	\$ 2,186	\$ 2,110	\$ 2,154	\$ 2,140	\$ 2,162	\$ 2,132	\$ 2,180	\$ 2,114	\$ 2,153	\$ 2,139
Irrigation Main Line Replacement	\$ 10,107	\$ 10,904	\$ 11,100	\$ 11,039	\$ 11,262	\$ 10,872	\$ 11,099	\$ 11,025	\$ 11,141	\$ 10,982	\$ 11,230	\$ 10,894	\$ 11,092	\$ 11,020
Irrigation Spray Heads Replacement	\$ 368	\$ 357	\$ 363	\$ 361	\$ 417	\$ 403	\$ 411	\$ 409	\$ 413	\$ 461	\$ 471	\$ 457	\$ 465	\$ 462

Prepared by Great Boards, LLC

High Desert Residential Owners Association, Inc. Funding Adjusted Revenue by Fiscal Calendar Year - Continued

Item Name	FY 2036	FY 2037	FY 2038	FY 2039	FY 2040	FY 2041	FY 2042	FY 2043	FY 2044	FY 2045	FY 2046	FY 2047	FY 2048	FY 2049
Irrigation System Common Area Allowance	\$ 920	\$ 892	\$ 908	\$ 903	\$ 922	\$ 890	\$ 908	\$ 902	\$ 912	\$ 1,154	\$ 1,180	\$ 1,145	\$ 1,166	\$ 1,158
Irrigation System Pinion Point Park Replacement	\$ 1,444	\$ 1,400	\$ 1,426	\$ 1,418	\$ 1,446	\$ 1,396	\$ 1,425	\$ 1,416	\$ 1,431	\$ 1,410	\$ 1,442	\$ 1,399	\$ 1,425	\$ 1,415
Irrigation Valve Boxes Replacement	\$ 1,850	\$ 1,795	\$ 1,827	\$ 1,817	\$ 2,379	\$ 2,297	\$ 2,345	\$ 2,329	\$ 2,354	\$ 2,320	\$ 2,373	\$ 2,301	\$ 2,343	\$ 2,328
Irrigation Valves Replacement	\$ 33,218	\$ 32,219	\$ 32,797	\$ 32,617	\$ 33,276	\$ 38,261	\$ 39,060	\$ 38,798	\$ 39,207	\$ 38,649	\$ 39,521	\$ 38,338	\$ 46,491	\$ 46,189
Irrigation Water Meters Replacement	\$ 6,946	\$ 6,737	\$ 6,858	\$ 6,820	\$ 6,958	\$ 6,717	\$ 6,857	\$ 6,811	\$ 6,883	\$ 6,785	\$ 6,938	\$ 11,091	\$ 11,293	\$ 11,219
Landscape Decomposed Granite Refurbishment	\$ 779	\$ 756	\$ 809	\$ 804	\$ 862	\$ 832	\$ 893	\$ 887	\$ 943	\$ 930	\$ 999	\$ 969	\$ 1,038	\$ 1,031
Landscaping Plant Material Replacement	\$ 3,170	\$ 3,074	\$ 3,129	\$ 3,995	\$ 4,076	\$ 3,935	\$ 4,017	\$ 3,990	\$ 4,032	\$ 3,975	\$ 4,065	\$ 3,943	\$ 4,015	\$ 5,120
Landscaping Turf Pinion Point Park Replacement	\$ 6,364	\$ 6,993	\$ 7,119	\$ 7,080	\$ 7,223	\$ 6,973	\$ 8,065	\$ 8,011	\$ 8,095	\$ 7,980	\$ 8,160	\$ 8,969	\$ 9,132	\$ 9,072
Landscaping & Irrigation Subtotal :	\$ 74,883	\$ 77,330	\$ 78,756	\$ 79,207	\$ 81,424	\$ 84,741	\$ 88,456	\$ 87,865	\$ 88,838	\$ 87,881	\$ 89,914	\$ 92,635	\$ 101,828	\$ 102,296
					Reserve (Category : Lar	ndscaping & li	rrigation						
Accent Lights Replacement	\$ 355	\$ 345	\$ 351	\$ 349	\$ 356	\$ 344	\$ 351	\$ 348	\$ 352	\$ 347	\$ 456	\$ 442	\$ 450	\$ 447
					F	Reserve Categ	orv : Liahtina							
Metal Fences and Gates Painting	\$ 6,468	\$ 6,273	\$ 6,386	\$ 6,351	\$ 6,479	\$ 6,255	\$ 6,385	\$ 7,554	\$ 7,634	\$ 7,525	\$ 7,695	\$ 7,465	\$ 7,600	\$ 7,551
Ramada Chamisa Park Refurbishment	\$ 170	\$ 164	\$ 167	\$ 166	\$ 170	\$ 164	\$ 167	\$ 166	\$ 168	\$ 166	\$ 169	\$ 164	\$ 312	\$ 310
Ramada Pinon Point Park Refurbishment	\$ 135	\$ 131	\$ 133	\$ 132	\$ 135	\$ 130	\$ 133	\$ 132	\$ 134	\$ 132	\$ 135	\$ 131	\$ 133	\$ 247
Stucco Walls Painting	\$ 26,181	\$ 25,393	\$ 25,849	\$ 25,706	\$ 33,665	\$ 32,500	\$ 33,178	\$ 32,956	\$ 33,303	\$ 32,830	\$ 33,570	\$ 32,565	\$ 33,157	\$ 32,942
Stucco Walls Repairs	\$ 1,745	\$ 1,693	\$ 1,723	\$ 1,713	\$ 2,244	\$ 2,167	\$ 2,212	\$ 2,197	\$ 2,220	\$ 2,189	\$ 2,238	\$ 2,171	\$ 2,210	\$ 2,196
Painting & Repairs Subtotal :	\$ 34,699	\$ 33,654	\$ 34,258	\$ 34,068	\$ 42,693	\$ 41,216	\$ 42,075	\$ 43,005	\$ 43,459	\$ 42,842	\$ 43,807	\$ 42,496	\$ 43,412	\$ 43,246

Prepared by Great Boards, LLC

High Desert Residential Owners Association, Inc. Funding Adjusted Revenue by Fiscal Calendar Year - Continued

Item Name	FY 2036	FY 2037	FY 2038	FY 2039	FY 2040	FY 2041	FY 2042	FY 2043	FY 2044	FY 2045	FY 2046	FY 2047	FY 2048	FY 2049
					Reser	ve Category :	Painting & Re	pairs						
Art Restoration	\$ 258	\$ 251	\$ 255	\$ 254	\$ 259	\$ 250	\$ 255	\$ 253	\$ 256	\$ 252	\$ 258	\$ 413	\$ 420	\$ 417
Park Furniture Chamisa Park Replacement	\$ 78	\$ 75	\$ 77	\$ 76	\$ 78	\$ 75	\$ 77	\$ 76	\$ 77	\$ 76	\$ 78	\$ 75	\$ 77	\$ 76
Park Furniture Medara Park Replacement	\$ 159	\$ 155	\$ 157	\$ 156	\$ 160	\$ 154	\$ 157	\$ 156	\$ 158	\$ 156	\$ 159	\$ 154	\$ 157	\$ 156
Park Furniture Pinion Point Park Replacement	\$ <i>55</i>	\$ 53	\$ 54	\$ 54	\$ 55	\$ 53	\$ 54	\$ 54	\$ <i>55</i>	\$ 54	\$ 55	\$ 53	\$ 54	\$ 54
Play Equipment Pinion Point Park Replacement	\$ 2,000	\$ 1,940	\$ 1,975	\$ 1,964	\$ 2,004	\$ 1,934	\$ 1,975	\$ 1,962	\$ 1,982	\$ 2,842	\$ 2,906	\$ 2,819	\$ 2,870	\$ 2,852
Park Furniture & Elements Subtotal :	\$ 2,550	\$ 2,474	\$ 2,518	\$ 2,504	\$ 2,556	\$ 2,466	\$ 2,518	\$ 2,501	\$ 2,528	\$ 3,380	\$ 3,456	\$ 3,514	\$ 3,578	\$ 3,555
					Reserve C	ategory : Park	k Furniture & I	Elements						
Monument Chaco Ridge & Compound Refurbishment	\$ 62	\$ 60	\$ 61	\$ 61	\$ 62	\$ 60	\$ 61	\$ 61	\$ 62	\$ 61	\$ 62	\$ 60	\$ 83	\$ 82
Monument Chamisa Trail Refurbishment	\$ 62	\$ 60	\$ 61	\$ 61	\$ 62	\$ 60	\$ 61	\$ 61	\$ 62	\$ 61	\$ 62	\$ 60	\$ 83	\$ 82
Monument Desert Highlands at High Desert Refurbishment	\$ 676	\$ 656	\$ 667	\$ 664	\$ 913	\$ 882	\$ 900	\$ 894	\$ 904	\$ 891	\$ 911	\$ 884	\$ 900	\$ 894
Monument Desert Mountain at High Desert Refurbishment	\$ 101	\$ 98	\$ 100	\$ 99	\$ 137	\$ 132	\$ 135	\$ 134	\$ 136	\$ 134	\$ 137	\$ 133	\$ 135	\$ 134
Monument Desert Sky Refurbishment	\$ 62	\$ 60	\$ 61	\$ 61	\$ 62	\$ 60	\$ 61	\$ 61	\$ 62	\$ 61	\$ 62	\$ 60	\$ 83	\$ 82
Monument Desert Song Refurbishment	\$ 67	\$ 65	\$ 67	\$ 66	\$ 68	\$ 65	\$ 67	\$ 66	\$ 86	\$ 85	\$ 87	\$ 84	\$ 86	\$ 85
Monument High Desert Refurbishment	\$ 3,092	\$ 2,999	\$ 3,919	\$ 3,897	\$ 3,976	\$ 3,838	\$ 3,918	\$ 3,892	\$ 3,933	\$ 3,877	\$ 3,965	\$ 3,846	\$ 5,026	\$ 4,994
Monument High Desert Park Refurbishment	\$ 920	\$ 892	\$ 908	\$ 903	\$ 922	\$ 890	\$ 908	\$ 902	\$ 912	\$ 1,154	\$ 1,180	\$ 1,145	\$ 1,166	\$ 1,158

Prepared by Great Boards, LLC

High Desert Residential Owners Association, Inc. Funding Adjusted Revenue by Fiscal Calendar Year - Continued

Item Name	FY 2036	FY 2037	FY 2038	FY 2039	FY 2040	FY 2041	FY 2042	FY 2043	FY 2044	FY 2045	FY 2046	FY 2047	FY 2048	FY 2049
Monument Highlands at High Desert Refurbishment	\$ 676	\$ 656	\$ 667	\$ 664	\$ 913	\$ 882	\$ 900	\$ 894	\$ 904	\$ 891	\$ 911	\$ 884	\$ 900	\$ 894
Monument Michial Emery - Bear Canyon Trailhead Replacement	<i>\$ 53</i>	\$ <i>52</i>	\$ <i>52</i>	\$ 52	\$ 53	\$ 51	\$ 71	\$ 70	\$ 71	\$ 70	\$ 71	\$ 69	\$ 71	\$ 70
Monument Mountain Highlands at High Desert Refurbishment	\$ 676	\$ <i>656</i>	\$ 667	\$ 664	\$ 913	\$ 882	\$ 900	\$ 894	\$ 904	\$ 891	\$ 911	\$ 884	\$ 900	\$ 894
Monument Overlook at High Desert Refurbishment	\$ 676	\$ 656	\$ 667	\$ 664	\$ 913	\$ 882	\$ 900	\$ 894	\$ 904	\$ 891	\$ 911	\$ 884	\$ 900	\$ 894
Monument Pinon Point Refurbishment	\$ 70	\$ 68	\$ 70	\$ 69	\$ 71	\$ 68	\$ 70	\$ 69	\$ 70	\$ 69	\$ 70	\$ 68	\$ 95	\$ 94
Monument Solterra Refurbishment	\$ 51	\$ 50	\$ 50	\$ 50	\$ 69	\$ 66	\$ 68	\$ 67	\$ 68	\$ 67	\$ 68	\$ 66	\$ 67	\$ 67
Monument Sunset Ridge Refurbishment	\$ 62	\$ 60	\$ 61	\$ 61	\$ 62	\$ 60	\$ 61	\$ 61	\$ 62	\$ 61	\$ 62	\$ 60	\$ 83	\$ 82
Monument The Aerie Refurbishment	\$ 52	\$ 51	\$ 51	\$ 51	\$ 52	\$ 68	\$ 70	\$ 69	\$ 70	\$ 69	\$ 70	\$ 68	\$ 70	\$ 69
Monument The Canyons at High Desert Refurbishment	\$ 54	\$ 52	<i>\$ 53</i>	\$ 53	\$ 54	\$ 52	\$ 53	\$ 72	\$ 73	\$ 72	\$ 73	\$ 71	\$ 73	\$ 72
Monument The Enclave at High Desert Refurbishment	\$ 67	\$ 65	\$ 67	\$ 85	\$ 87	\$ 84	\$ 86	\$ 85	\$ 86	\$ 85	\$ 87	\$ 84	\$ 86	\$ 109
Monument The Legends at High Desert Refurbishment	\$ 70	\$ 68	\$ 70	\$ 69	\$ 71	\$ 68	\$ 70	\$ 69	\$ 70	\$ 69	\$ 70	\$ 68	\$ 95	\$ 94
Monument The Trillium at High Desert Refurbishment	\$ 43	\$ 60	\$ 61	\$ 61	\$ 62	\$ 60	\$ 61	\$ 61	\$ 62	\$ 61	\$ 62	\$ 60	\$ 61	\$ 61
Monument Tierra Del Oso Refurbishment	\$ 47	\$ 46	\$ 46	\$ 46	\$ 47	\$ 45	\$ 46	\$ 46	\$ 47	\$ 46	\$ 47	\$ 46	\$ 62	\$ 62
Monument Trailhead at High Desert Refurbishment	\$ 676	\$ 656	\$ 667	\$ 664	\$ 913	\$ 882	\$ 900	\$ 894	\$ 904	\$ 891	\$ 911	\$ 884	\$ 900	\$ 894

Prepared by Great Boards, LLC

High Desert Residential Owners Association, Inc. Funding Adjusted Revenue by Fiscal Calendar Year - Continued

Item Name	FY 2036	FY 2037	FY 2038	FY 2039	FY 2040	FY 2041	FY 2042	FY 2043	FY 2044	FY 2045	FY 2046	FY 2047	FY 2048	FY 2049
Monument West Highlands at High Desert Refurbishment	\$ 676	\$ 656	\$ 667	\$ 664	\$ 913	\$ 882	\$ 900	\$ 894	\$ 904	\$ 891	\$ 911	\$ 884	\$ 900	\$ 894
Monument Wilderness At High Desert Refurbishment	\$ 58	\$ 56	\$ 57	\$ 57	\$ 79	\$ 76	\$ 78	\$ 77	\$ 78	\$ 77	\$ 79	\$ 76	\$ 78	\$ 77
Monument Wilderness Canon Refurbishment	\$ 51	\$ 50	\$ 50	\$ 50	\$ 51	\$ 49	\$ 50	\$ 50	\$ 51	\$ 50	\$ 51	\$ 49	\$ 50	\$ 72
Monument Wilderness Compound Refurbishment	\$ 51	\$ 50	\$ 50	\$ 50	\$ 51	\$ 49	\$ 50	\$ 50	\$ 51	\$ 50	\$ 51	\$ 49	\$ 50	\$ 72
Monument Wilderness Estates at High Desert Refurbishment	\$ 944	\$ 915	\$ 932	\$ 926	\$ 945	\$ 912	\$ 931	\$ 925	\$ 935	\$ 922	\$ 1,211	\$ 1,174	\$ 1,196	\$ 1,188
Monument Wilderness Village Refurbishment	\$ 62	\$ 60	\$ 61	\$ 61	\$ 62	\$ 60	\$ 61	\$ 61	\$ 62	\$ 61	\$ 62	\$ 60	\$ 83	\$ 82
Signs Hiking Trail Replacement	\$ 957	\$ 928	\$ 945	\$ 939	\$ 958	\$ 925	\$ 945	\$ 938	\$ 948	\$ 1,540	\$ 1,575	\$ 1,528	\$ 1,556	\$ 1,545
Signs Pet Waste Stations Replacement	\$ 1,212	\$ 1,176	\$ 1,197	\$ 1,190	\$ 1,214	\$ 1,172	\$ 1,197	\$ 1,189	\$ 1,201	\$ 1,184	\$ 1,211	\$ 1,174	\$ 1,196	\$ 1,188
Signage Subtotal :	\$ 12,326	\$ 11,977	\$ 13,052	\$ 13,002	\$ 14,755	\$ 14,262	\$ 14,579	\$ 14,500	\$ 14,682	\$ 15,332	\$ 15,941	\$ 15,462	\$ 17,034	\$ 16,985
					F	Reserve Categ	ory : Signage							
Fence Metal Perimeter Desert Mountain Replacement	\$ 210	\$ 204	\$ 208	\$ 207	\$ 211	\$ 203	\$ 208	\$ 206	\$ 208	\$ 205	\$ 210	\$ 204	\$ 208	\$ 206
Fence Metal Perimeter Solterra Replacement	\$ 40	\$ 39	\$ 39	\$ 39	\$ 40	\$ 39	\$ 39	\$ 39	\$ 39	\$ 39	\$ 40	\$ 39	\$ 39	\$ 39
Fence Metal Perimeter The Canyons Replacement	\$ 4,517	\$ 4,382	\$ 4,460	\$ 4,436	\$ 4,525	\$ 4,369	\$ 4,460	\$ 4,430	\$ 4,477	\$ 4,413	\$ 4,512	\$ 4,377	\$ 4,457	\$ 4,428
Fence Metal Perimeter The Enclave Replacement	\$ 87	\$ 84	\$ 86	\$ 85	\$ 87	\$ 84	\$ 86	\$ 85	\$ 86	\$ 85	\$ 87	\$ 84	\$ 86	\$ 85
Fence Metal Perimeter The Legends Replacement	\$ 95	\$ 92	\$ 94	\$ 93	\$ 95	\$ 92	\$ 94	\$ 93	\$ 94	\$ 93	\$ 95	\$ 92	\$ 94	\$ 93
Fence Metal Perimeter The Trillium Replacement	\$ 570	\$ 553	\$ 563	\$ 559	\$ 571	\$ 551	\$ 563	\$ 559	\$ 565	\$ 557	\$ 569	\$ 552	\$ 562	\$ 559

Prepared by Great Boards, LLC

High Desert Residential Owners Association, Inc. Funding Adjusted Revenue by Fiscal Calendar Year - Continued

Item Name	FY 2036	FY 2037	FY 2038	FY 2039	FY 2040	FY 2041	FY 2042	FY 2043	FY 2044	FY 2045	FY 2046	FY 2047	FY 2048	FY 2049
Fence Metal Perimeter Tierra Del Oso Replacement	\$ 2,179	\$ 2,114	\$ 2,151	\$ 2,140	\$ 2,183	\$ 2,107	\$ 2,151	\$ 2,137	\$ 2,159	\$ 2,129	\$ 2,177	\$ 2,112	\$ 2,150	\$ 2,136
Fence Metal Perimeter Tramway Replacement														
Fence Metal Perimeter Wilderness Replacement	\$ 244	\$ 237	\$ 241	\$ 240	\$ 244	\$ 236	\$ 241	\$ 239	\$ 242	\$ 238	\$ 244	\$ 236	\$ 241	\$ 239
Fence Metal Perimeter Wilderness Compound Replacement	\$ 193	\$ 187	\$ 191	\$ 189	\$ 193	\$ 187	\$ 191	\$ 189	\$ 191	\$ 189	\$ 193	\$ 187	\$ 190	\$ 189
Fence Metal Pipe Rail Replacement	\$ 581	\$ 564	\$ 574	\$ 570	\$ 582	\$ 562	\$ 574	\$ 570	\$ 576	\$ 568	\$ 580	\$ 563	\$ 573	\$ 570
Fence Range Open Range Replacement Future	\$ 8,347	\$ 8,096	\$ 8,241	\$ 8,196	\$ 8,361	\$ 8,072	\$ 8,240	\$ 8,185	\$ 8,271	\$ 8,154	\$ 8,338	\$ 8,088	\$ 8,235	\$ 8,182
Gates Metal Access Replacement	\$ 825	\$ 800	\$ 815	\$ 810	\$ 826	\$ 798	\$ 815	\$ 809	\$ 818	\$ 806	\$ 824	\$ 799	\$ 814	\$ 809
Gates Metal Michial Emery Trailhead Replacement	\$81	\$ 78	\$ 80	\$ 79	\$81	\$ 78	\$ 80	<i>\$ 79</i>	\$ 80	\$ 79	\$81	<i>\$ 78</i>	\$ 80	\$ 79
Fences & Gates Subtotal :	\$ 17,969	\$ 17,430	\$ 17,743	\$ 17,643	\$ 17,999	\$ 17,378	\$ 17,742	\$ 17,620	\$ 17,806	\$ 17,555	\$ 17,950	\$ 17,411	\$ 17,729	\$ 17,614
Total Revenue :	\$ 159,902	\$ 159,902	\$ 163,678	\$ 163,678	\$ 177,835	\$ 177,835	\$ 183,620	\$ 183,620	\$ 185,620	\$ 185,620	\$ 190,224	\$ 190,224	\$ 202,619	\$ 202,619

Item Name	FY 2050	FY 2051
Reserve Category : Asphalt	t & Concrete	
Asphalt Cracksealing & Repairs Michial Emery Trailhead	\$ 1,036	\$ 1,036
Asphalt Cracksealing & Repairs Trail	\$ 701	\$ 701
Asphalt Resurfacing Michial Emery Trailhead	\$ 2,322	\$ 2,322
Asphalt Resurfacing Trail	\$ 8,940	\$ 8,940
Asphalt Sealcoating Michial Emery Trailhead	\$ 1,412	\$ 1,412
Asphalt Sealcoating Trail	\$ 3,553	\$ 3,553
Concrete Sidewalks Repairs	\$ 1,579	\$ 1,579
Asphalt & Concrete Subtotal :	\$ 19,543	\$ 19,543
Reserve Category	: Fences & Ga	ites
Irrigation Backflow Preventers Replacement	\$ 6,220	\$ 6,220
Irrigation Controllers Pinion Point Park Unfunded		
Irrigation Controllers Replacement	\$ 4,312	\$ 4,312
Irrigation Flow Meters Replacement	\$ 643	\$ 643
Irrigation Lateral Line Replacement	\$ 2,145	\$ 2,145
Irrigation Main Line Replacement	\$ 11,052	\$ 11,052
Irrigation Spray Heads Replacement	\$ <i>525</i>	\$ <i>525</i>

Prepared by Great Boards, LLC

Item Name	FY 2050	FY 2051
Irrigation System Common Area Allowance	\$ 1,161	\$ 1,161
Irrigation System Pinion Point Park Replacement	\$ 1,419	\$ 1,419
Irrigation Valve Boxes Replacement	\$ 2,997	\$ 2,997
Irrigation Valves Replacement	\$ 46,325	\$ 46,325
Irrigation Water Meters Replacement	\$ 11,252	\$ 11,252
Landscape Decomposed Granite Refurbishment	\$ 1,086	\$ 1,086
Landscaping Plant Material Replacement	\$ 5,135	\$ 5,135
Landscaping Turf Pinion Point Park Replacement	\$ 9,099	\$ 9,099
Landscaping & Irrigation Subtotal :	\$ 103,371	\$ 103,371
Reserve Category : Lar	ndscanina & Ir	rigation
Accent Lights Replacement	\$ 449	\$ 449
Reserve Categ	ory : Lighting	
Metal Fences and Gates Painting	\$ 9,021	\$ 9,021
Ramada Chamisa Park Refurbishment	\$ 311	\$ 311
Ramada Pinon Point Park Refurbishment	\$ 248	\$ 248
Stucco Walls Painting	\$ 42,412	\$ 42,412
Stucco Walls Repairs	\$ 2,827	\$ 2,827
Painting & Repairs Subtotal :	\$ 54,819	\$ 54,819

Prepared by Great Boards, LLC

Item Name	FY 2050	FY 2051
Reserve Category :	Painting & Re	pairs
Art Restoration	\$ 419	\$ 419
Park Furniture Chamisa Park Replacement	\$ 76	\$ 76
Park Furniture Medara Park Replacement	\$ 157	\$ 157
Park Furniture Pinion Point Park Replacement	\$ 54	\$ 54
Play Equipment Pinion Point Park Replacement	\$ 2,860	\$ 2,860
Park Furniture & Elements Subtotal :	\$ 3,566	\$ 3,566
Reserve Category : Park	r Furniture & E	Elements
Monument Chaco Ridge & Compound Refurbishment	\$ 82	\$ 82
Monument Chamisa Trail Refurbishment	\$ 82	\$ 82
Monument Desert Highlands at High Desert Refurbishment	\$ 896	\$ 896
Monument Desert Mountain at High Desert Refurbishment	\$ 135	\$ 135
Monument Desert Sky Refurbishment	\$ 82	\$ 82
Monument Desert Song Refurbishment	\$ 85	\$ 85
Monument High Desert Refurbishment	\$ 5,008	\$ 5,008
Monument High Desert Park Refurbishment	\$ 1,161	\$ 1,161

Prepared by Great Boards, LLC

Item Name	FY 2050	FY 2051
Monument Highlands at High Desert Refurbishment	\$ 896	\$ 896
Monument Michial Emery - Bear Canyon Trailhead Replacement	\$ 70	\$ 70
Monument Mountain Highlands at High Desert Refurbishment	\$ 896	\$ 896
Monument Overlook at High Desert Refurbishment	\$ 896	\$ 896
Monument Pinon Point Refurbishment	\$ 94	\$ 94
Monument Solterra Refurbishment	\$ 67	\$ 67
Monument Sunset Ridge Refurbishment	\$ 82	\$ 82
Monument The Aerie Refurbishment	\$ 69	\$ 69
Monument The Canyons at High Desert Refurbishment	\$ 72	\$ 72
Monument The Enclave at High Desert Refurbishment	\$ 109	\$ 109
Monument The Legends at High Desert Refurbishment	\$ 94	\$ 94
Monument The Trillium at High Desert Refurbishment	\$ 61	\$ 61
Monument Tierra Del Oso Refurbishment	\$ 62	\$ 62
Monument Trailhead at High Desert Refurbishment	\$ 896	\$ 896

Prepared by Great Boards, LLC

Item Name	FY 2050	FY 2051
Monument West Highlands at High Desert Refurbishment	\$ 896	\$ 896
Monument Wilderness At High Desert Refurbishment	\$ 77	\$ 77
Monument Wilderness Canon Refurbishment	\$ 72	\$ 72
Monument Wilderness Compound Refurbishment	\$ 72	\$ 72
Monument Wilderness Estates at High Desert Refurbishment	\$ 1,192	\$ 1,192
Monument Wilderness Village Refurbishment	\$ 82	\$ 82
Signs Hiking Trail Replacement	\$ 1,550	\$ 1,550
Signs Pet Waste Stations Replacement	\$ 1,192	\$ 1,192
Signage Subtotal :	\$ 17,028	\$ 17,028
Reserve Categ	ory : Signage	
Fence Metal Perimeter Desert Mountain Replacement	\$ 207	\$ 207
Fence Metal Perimeter Solterra Replacement	\$ 39	\$ 39
Fence Metal Perimeter The Canyons Replacement	\$ 4,441	\$ 4,441
Fence Metal Perimeter The Enclave Replacement	\$ 85	\$ 85
Fence Metal Perimeter The Legends Replacement	\$ 93	\$ 93
Fence Metal Perimeter The Trillium Replacement	\$ 560	\$ 560

Prepared by Great Boards, LLC

Item Name	FY 2050	FY 2051
Fence Metal Perimeter Tierra Del Oso Replacement	\$ 2,142	\$ 2,142
Fence Metal Perimeter Tramway Replacement		
Fence Metal Perimeter Wilderness Replacement	\$ 240	\$ 240
Fence Metal Perimeter Wilderness Compound Replacement	\$ 190	\$ 190
Fence Metal Pipe Rail Replacement	\$ 571	\$ 571
Fence Range Open Range Replacement Future	\$ 8,206	\$ 8,206
Gates Metal Access Replacement	\$ 811	\$ 811
Gates Metal Michial Emery Trailhead Replacement	\$ 79	\$ 79
Fences & Gates Subtotal :	\$ 17,664	\$ 17,664
Total Revenue :	\$ 216,449	\$ 216,449

High Desert Residential Owners Association, Inc. Funding Study - Expenses by Item and by Fiscal Calendar Year

Item Description	FY 2021	FY 2022	FY 2023	FY 2024	FY 2025	FY 2026	FY 2027	FY 2028	FY 2029	FY 2030	FY 2031	FY 2032	FY 2033	FY 2034	FY 2035	FY 2036	FY 2037	FY 2038	FY 2039	FY 2040	FY 2041
								Res	erve Category :	Asphalt & Cond	rete										
Asphalt Cracksealing & Repairs Michial Emery Trailhead	\$ 2,451					\$ 2,778					\$ 3,147					\$ 3,565					\$ 4,040
Asphalt Cracksealing & Repairs Trail				\$ 1,658					\$ 1,878					\$ 2,128					\$ 2,411		
Asphalt Resurfacing Michial Emery Trailhead									\$ 33,802												
Asphalt Resurfacing Trail														\$ 130,166							
Asphalt Sealcoating Michial Emery Trailhead				\$ 3,342					\$ 3,786					\$ 4,290					\$ 4,860		
Asphalt Sealcoating Trail				\$ 8,407					\$ 9,525					\$ 10,792					\$ 12,228		
Concrete Sidewalks Repairs									\$ 7,512										\$ 9,643		
Category Subtotal :	\$ 2,451			\$ 13,407		\$ 2,778			\$ 56,503		\$ 3,147			\$ 147,376		\$ 3,565			\$ 29,142		\$ 4,040
								R	eserve Category	: Fences & Gai	'es										
Fence Metal Perimeter Desert Mountain Replacement																					
Fence Metal Perimeter Solterra Replacement																					
Fence Metal Perimeter The Canyons Replacement																					
Fence Metal Perimeter The Enclave Replacement																					
Fence Metal Perimeter The Legends Replacement																					
Fence Metal Perimeter The Trillium Replacement																					
Fence Metal Perimeter Tierra Del Oso Replacement																					
Fence Metal Perimeter Tramway Replacement																					
Fence Metal Perimeter Wilderness Replacement																					
Fence Metal Perimeter Wilderness Compound Replacement																					
Fence Metal Pipe Rail Replacement									\$ 7,813												
Fence Range Open Range Replacement Future												\$ 101,208									
Gates Metal Access Replacement																					
Gates Metal Michial Emery Trailhead Replacement																					
Category Subtotal :									\$ 7,813			\$ 101,208									
								Reserv	re Category : La	ndscaping & Irr	igation										
Irrigation Backflow Preventers Replacement	\$ 44,600															\$ 64,867					
Irrigation Controllers Pinion Point Park Unfunded																					

The contribution of the co	Item Description	FY 2021	FY 2022	FY 2023	FY 2024	FY 2025	FY 2026	FY 2027	FY 2028	FY 2029	FY 2030	FY 2031	FY 2032	FY 2033	FY 2034	FY 2035	FY 2036	FY 2037	FY 2038	FY 2039	FY 2040	FY 2041
Proper Service Analysis Angeword 54,000 10 10 10 10 10 10 10	Irrigation Controllers Replacement	\$ 20,506										\$ 26,323										\$ 33,791
Page	Irrigation Flow Meters Replacement	\$ 4,614															\$ 6,710					
Part	Irrigation Lateral Line Replacement	\$ 15,379															\$ 22,368					
Property Separation Assessed 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Irrigation Main Line Replacement																\$ 160,908					
The contribute of the contribu	Irrigation Spray Heads Replacement				\$ 1,243					\$ 1,409					\$ 1,596					\$ 1,808		
Reparament of the first of the	Irrigation System Common Area Allowance				\$ 5,525										\$ 7,093							
Pages Prince Pri	Irrigation System Pinion Point Park Replacement									\$ 20,658												
Institution Processing Services (1988) 1	Irrigation Valve Boxes Replacement									\$ 14,254										\$ 18,298		
State Stat	Irrigation Valves Replacement						\$ 161,644							\$ 192,523							\$ 229,300	
Note obtained (Systems 1 1998)	Irrigation Water Meters Replacement						\$ 84,220															
Ministry Information 1972	Landscape Decomposed Granite Refurbishment	\$ 1,025		\$ 1,078		\$ 1,133		\$ 1,191		\$ 1,252		\$ 1,316		\$ 1,384		\$ 1,454		\$ 1,529		\$ 1,607		\$ 1,690
Replacement \$2.03 \$1,000 \$	Landscaping Plant Material Replacement								\$ 24,423										\$ 31,352			
Accord Light Professionered Company Comp	Landscaping Turf Pinion Point Park Replacement	\$ 21,531					\$ 24,395					\$ 27,639					\$ 31,315					\$ 35,480
Account lights Replacement	Category Subtotal :	\$ 107,655		\$ 1,078	\$ 6,768	\$ 1,133	\$ 270,259	\$ 1,191	\$ 24,423	\$ 37,573		\$ 55,278		\$ 193,907	\$ 8,689	\$ 1,454	\$ 286,168	\$ 1,529	\$ 31,352	\$ 21,713	\$ 229,300	\$ 70,961
Account lights Replacement										Reserve Categ	ory : Lighting											
Media Ferces and Gales Painting	Accent Lights Replacement					\$ 2,136										\$ 2,742						
Ramada Chamisa Plank Redutsishment \$ \$ \$ \$ \$ \$ \$ \$ \$									Res	erve Category :	Painting & Rep	pairs										
Ramada Priori Park Refurberiment Succo Walls Painting Succo Walls Painting Succo Walls Repairs Succo W	Metal Fences and Gates Painting	\$ 26,427							\$ 31,475							\$ 37,488						
Slucco Walls Painting Slucco Walls Repairs Sluc	Ramada Chamisa Park Refurbishment		\$ 2,281																			
State Or Walfs Regulars Category Subtolat: \$26,427 \$2,281 \$1,813 \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	Ramada Pinon Point Park Refurbishment			\$ 1,813																		
Category Subtotals S 26,427 S 2,281 S 1,813 S 3 1,475 S 215,168 S 31,475 S 215,168 S 37,488 S 37,488 S 276,209 S 2	Stucco Walls Painting									\$ 201,721										\$ 258,947		
Reserve Category : Park Furniture & Bioments	Stucco Walls Repairs									\$ 13,447										\$ 17,262		
Art Restoration	Category Subtotal :	\$ 26,427	\$ 2,281	\$ 1,813					\$ 31,475	\$ 215,168						\$ 37,488				\$ 276,209		
Art Restoration									Reserve	e Category : Par	k Furniture & E	lements										
Park Furniture Median Park Replacement Image: Control of the Park Replacement Image:	Art Restoration						\$ 3,136															
Park Furniture Pinion Point Park Replacement Image: Control of the Park Replacement Image: Control of the Park Replacement \$ 20,508 Image: Control of the Park Replacement Image: Control of the Park Replacement \$ 20,508 Image: Control of the Park Replacement Image	Park Furniture Chamisa Park Replacement																					
Replacement <td< td=""><td>Park Furniture Medara Park Replacement</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></td<>	Park Furniture Medara Park Replacement																					
Replacement \$ 20,008 \$ 1 \$ 20,508 \$ 1 \$ 1 \$ 1 \$ 20,508 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 20,508 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 20,508 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 20,508 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 20,508 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 20,508	Park Furniture Pinion Point Park Replacement																					
Reserve Category : Signage Monument Chaco Ridge & Compound Refurbishment \$404	Play Equipment Pinion Point Park Replacement									\$ 20,508												
Monument Chaco Ridge & Compound Refurbishment \$ 404	Category Subtotal :						\$ 3,136			\$ 20,508												
Monument Chaco Ridge & Compound Refurbishment \$ 404										Reserve Categ	ory : Signage											
Monument Chamisa Trail Refurbishment \$404	Monument Chaco Ridge & Compound Refurbishment			\$ 404							, 000					\$ 545						
	Monument Chamisa Trail Refurbishment			\$ 404												\$ 545						

Item Description	FY 2021	FY 2022 FY 2023	FY 2024	FY 2025	FY 2026	FY 2027	FY 2028	FY 2029	FY 2030	FY 2031	FY 2032	FY 2033	FY 2034	FY 2035	FY 2036	FY 2037	FY 2038	FY 2039	FY 2040	FY 2041
Monument Desert Highlands at High Desert Refurbishment						\$ 5,955												\$ 8,036		
Monument Desert Mountain at High Desert Refurbishment						\$ 893												\$ 1,205		
Monument Desert Sky Refurbishment		\$ 404												\$ 545						
Monument Desert Song Refurbishment		\$ 404										\$ 519								
Monument High Desert Refurbishment						\$ 23,821										\$ 30,578				
Monument High Desert Park Refurbishment			\$ 5,525										\$ 7,093							
Monument Highlands at High Desert Refurbishment						\$ 5,955												\$ 8,036		
Monument Michial Emery - Bear Canyon Trailhead Replacement								\$ 470												\$ 634
Monument Mountain Highlands at High Desert Refurbishment						\$ 5,955												\$ 8,036		
Monument Overlook at High Desert Refurbishment						\$ 5,955												\$ 8,036		
Monument Pinon Point Refurbishment		\$ 463												\$ 625						
Monument Solterra Refurbishment						\$ 447												\$ 603		
Monument Sunset Ridge Refurbishment		\$ 404												\$ 545						
Monument The Aerie Refurbishment							\$ 458												\$ 618	
Monument The Canyons at High Desert Refurbishment									\$ 481											
Monument The Enclave at High Desert Refurbishment							\$ 519										\$ 666			
Monument The Legends at High Desert Refurbishment		\$ 463												\$ 625						
Monument The Trillium at High Desert Refurbishment	\$ 441														\$ 641					
Monument Tierra Del Oso Refurbishment		\$ 307												\$ 415						
Monument Trailhead at High Desert Refurbishment						\$ 5,955												\$ 8,036		
Monument West Highlands at High Desert Refurbishment						\$ 5,955												\$ 8,036		
Monument Wilderness At High Desert Refurbishment						\$ 512												\$ 691		
Monument Wilderness Canon Refurbishment												\$ 519								
Monument Wilderness Compound Refurbishment												\$ 519								
Monument Wilderness Estates at High Desert Refurbishment				\$ 5,665										\$ 7,272						
Monument Wilderness Village Refurbishment		\$ 404												\$ 545						
Signs Hiking Trail Replacement			\$ 11,603																	
Signs Pet Waste Stations Replacement																				

Item Description	FY 2021	FY 2022	FY 2023	FY 2024	FY 2025	FY 2026	FY 2027	FY 2028	FY 2029	FY 2030	FY 2031	FY 2032	FY 2033	FY 2034	FY 2035	FY 2036	FY 2037	FY 2038	FY 2039	FY 2040	FY 2041
Category Subtotal :	\$ 441		\$ 3,657	\$ 17,128	\$ 5,665		\$ 61,403	\$ 977	\$ 470	\$ 481			\$ 1,557	\$ 7,093	\$ 11,662	\$ 641	\$ 30,578	\$ 666	\$ 50,715	\$ 618	\$ 634
Expense Totals :	\$ 136,974	\$ 2,281	\$ 6,550	\$ 37,303	\$ 8,934	\$ 276,173	\$ 62,595	\$ 56,875	\$ 338,035	\$ 4 81	\$ 58,425	\$ 101,208	\$ 195,463	\$ 163,157	\$ 53,348	\$ 290,376	\$ 32,107	\$ 32,018	\$ 377,780	\$ 229,918	<i>\$ 75,634</i>

Item Description	FY 2042	FY 2043	FY 2044	FY 2045	FY 2046	FY 2047	FY 2048	FY 2049	FY 2050	FY 2051
			Reserve Cat	egory : Asphal	t & Concrete					
Asphalt Cracksealing & Repairs Michial Emery Trailhead					\$ 4,577					\$ 5,186
Asphalt Cracksealing & Repairs Trail			\$ 2,731					\$ 3,095		
Asphalt Resurfacing Michial Emery Trailhead										
Asphalt Resurfacing Trail										
Asphalt Sealcoating Michial Emery Trailhead			\$ 5,507					\$ 6,239		
Asphalt Sealcoating Trail			\$ 13,854					\$ 15,697		
Concrete Sidewalks Repairs								\$ 12,379		
Category Subtotal :			\$ 22,092		\$ 4,577			\$ 37,410		\$ 5,186
			Reserve C	ategory : Fenc	es & Gates					
Fence Metal Perimeter Desert Mountain Replacement										\$ 6,598
Fence Metal Perimeter Solterra Replacement										\$ 1,241
Fence Metal Perimeter The Canyons Replacement										\$ 141,474
Fence Metal Perimeter The Enclave Replacement										\$ 2,707
Fence Metal Perimeter The Legends Replacement										\$ 2,982
Fence Metal Perimeter The Trillium Replacement										\$ 17,837
Fence Metal Perimeter Tierra Del Oso Replacement										\$ 68,232
Fence Metal Perimeter Tramway Replacement										
Fence Metal Perimeter Wilderness Replacement										\$ 7,634
Fence Metal Perimeter Wilderness Compound Replacement										\$ 6,050
Fence Metal Pipe Rail Replacement										
Fence Range Open Range Replacement Future										
Gates Metal Access Replacement										
Gates Metal Michial Emery Trailhead Replacement										
Category Subtotal:										\$ 254,755
			Reserve Catea	ory : Landscan	ing & Irrigation					
Irrigation Backflow Preventers Replacement					J					\$ 94,345
Irrigation Controllers Pinion Point Park Unfunded										

Item Description	FY 2042	FY 2043	FY 2044	FY 2045	FY 2046	FY 2047	FY 2048	FY 2049	FY 2050	FY 2051
Irrigation Controllers Replacement										\$ 43,377
Irrigation Flow Meters Replacement										\$ 9,760
Irrigation Lateral Line Replacement										\$ 32,533
Irrigation Main Line Replacement										
Irrigation Spray Heads Replacement			\$ 2,049					\$ 2,321		
Irrigation System Common Area Allowance			\$ 9,105							
Irrigation System Pinion Point Park Replacement										
Irrigation Valve Boxes Replacement								\$ 23,489		
Irrigation Valves Replacement						\$ 273,103				
Irrigation Water Meters Replacement					\$ 138,783					
Landscape Decomposed Granite Refurbishment		\$ 1,776		\$ 1,867		\$ 1,963		\$ 2,063		\$ 2,169
Landscaping Plant Material Replacement							\$ 40,246			
Landscaping Turf Pinion Point Park Replacement					\$ 40,199					\$ 45,546
Category Subtotal :		\$ 1,776	\$ 11,154	\$ 1,867	\$ 178,982	\$ 275,066	\$ 40,246	\$ 27,873		\$ 227,730
			Pacar	ve Category : Li	ahtina					
Accent Lights Replacement			7000	\$ 3,519	grang					
			Reserve Ca	tegory : Paintin	g & Repairs					
Metal Fences and Gates Painting	\$ 44,649							\$ 53,178		
Ramada Chamisa Park Refurbishment						\$ 4,259				
Ramada Pinon Point Park Refurbishment							\$ 3,385			
Stucco Walls Painting								\$ 332,408		
Stucco Walls Repairs								\$ 22,158		
Category Subtotal :	\$ 44,649					\$ 4,259	\$ 3,385	\$ 407,744		
			Receive Catery	ory : Park Furnit	ura & Flamente					
Art Restoration			riboor vo ouloge	ny . r ank r anni	\$ 5,168					
Park Furniture Chamisa Park Replacement					, ,,					\$ 2,440
Park Furniture Medara Park Replacement										\$ 4,988
Park Furniture Pinion Point Park Replacement										\$ 1,735
Play Equipment Pinion Point Park Replacement			\$ 29,828							
Category Subtotal :			\$ 29,828		\$ 5,168					\$ 9,163
			Docom	ve Category : Si	angae					
Monument Chaco Ridge & Compound Refurbishment			noser	.o oatogory . Si	gnago	\$ 736				
Monument Chamisa Trail Refurbishment						\$ 736				
Monument Chamisa Hali Returbishiffett						ş / 3D				

Item Description	FY 2042	FY 2043	FY 2044	FY 2045	FY 2046	FY 2047	FY 2048	FY 2049	FY 2050	FY 2051
Monument Desert Highlands at High Desert Refurbishment										\$ 10,844
Monument Desert Mountain at High Desert Refurbishment										\$ 1,627
Monument Desert Sky Refurbishment						\$ 736				
Monument Desert Song Refurbishment		\$ 666								
Monument High Desert Refurbishment						\$ 39,253				
Monument High Desert Park Refurbishment			\$ 9,105							
Monument Highlands at High Desert Refurbishment										\$ 10,844
Monument Michial Emery - Bear Canyon Trailhead Replacement										
Monument Mountain Highlands at High Desert Refurbishment										\$ 10,844
Monument Overlook at High Desert Refurbishment										\$ 10,844
Monument Pinon Point Refurbishment						\$ 844				
Monument Solterra Refurbishment										\$ 813
Monument Sunset Ridge Refurbishment						\$ 736				
Monument The Aerie Refurbishment										
Monument The Canyons at High Desert Refurbishment	\$ 650									
Monument The Enclave at High Desert Refurbishment							\$ 855			
Monument The Legends at High Desert Refurbishment						\$ 844				
Monument The Trillium at High Desert Refurbishment										\$ 933
Monument Tierra Del Oso Refurbishment						\$ 559				
Monument Trailhead at High Desert Refurbishment										\$ 10,844
Monument West Highlands at High Desert Refurbishment										\$ 10,844
Monument Wilderness At High Desert Refurbishment										\$ 933
Monument Wilderness Canon Refurbishment							\$ 755			
Monument Wilderness Compound Refurbishment							<i>\$ 755</i>			
Monument Wilderness Estates at High Desert Refurbishment				\$ 9,335						
Monument Wilderness Village Refurbishment						\$ 736				
Signs Hiking Trail Replacement			\$ 19,120							
Signs Pet Waste Stations Replacement										\$ 37,955

Item Description	FY 2042	FY 2043	FY 2044	FY 2045	FY 2046	FY 2047	FY 2048	FY 2049	FY 2050	FY 2051
Category Subtotal :	\$ 650	\$ 666	\$ 28,225	\$ 9,335		\$ 45,180	\$ 2,365			\$ 107,325
Expense Totals :	\$ 45,299	\$ 2,442	\$ 91,299	\$ 14,722	\$ 188,727	\$ 324,505	\$ 45,995	\$ 473,028		\$ 604,156



30-Year Expense Summary

Year	Category	Item Name	Expense
	Asphalt & Concrete	Asphalt Cracksealing & Repairs Michial Emery Trailhead	\$ 2,451
		Irrigation Backflow Preventers Replacement	\$ 44,600
		Irrigation Controllers Replacement	\$ 20,506
		Irrigation Flow Meters Replacement	\$ 4,614
	Landscaping & Irrigation	Irrigation Lateral Line Replacement	\$ 15,379
FY 2021		Landscape Decomposed Granite Refurbishment	\$ 1,025
		Landscaping Turf Pinion Point Park Replacement	\$ 21,531
		Landscaping & Irrigation Subtotal = \$ 107,655.00	
	Painting & Repairs	Metal Fences and Gates Painting	\$ 26,427
	Signage	Monument The Trillium at High Desert Refurbishment	\$ 441
		FY 2021 Annual Expense To	otal = \$ 136,974
FY 2022	Painting & Repairs	Ramada Chamisa Park Refurbishment	\$ 2,281
		Annual Expense	Total = \$ 2,281
	Landscaping & Irrigation	Landscape Decomposed Granite Refurbishment	\$ 1,078
	Painting & Repairs	Ramada Pinon Point Park Refurbishment	\$ 1,813
FY 2023		Monument Chaco Ridge & Compound Refurbishment	\$ 404
	Signage	Monument Chamisa Trail Refurbishment	\$ 404
		Monument Desert Sky Refurbishment	\$ 404
		Monument Desert Song Refurbishment	\$ 404

Year	Category	Item Name	Expense
		Monument Pinon Point Refurbishment	\$ 463
		Monument Sunset Ridge Refurbishment	\$ 404
FY 2023	Signage	Monument The Legends at High Desert Refurbishment	\$ 463
		Monument Tierra Del Oso Refurbishment	\$ 307
		Monument Wilderness Village Refurbishment	\$ 404
		Signage Subtotal = \$ 3,657.00	
		FY 2023 Annual Expense	Total = \$ 6,548
		Asphalt Cracksealing & Repairs Trail	\$ 1,658
	Asphalt & Concrete	Asphalt Sealcoating Michial Emery Trailhead	\$ 3,342
		Asphalt Sealcoating Trail	\$ 8,407
		Asphalt & Concrete Subtotal = \$ 13,407.00	
EV 0004	Landscaping & Irrigation	Irrigation Spray Heads Replacement	\$ 1,243
FY 2024		Irrigation System Common Area Allowance	\$ 5,525
		Landscaping & Irrigation Subtotal = \$ 6,768.00	
	Cianaga	Monument High Desert Park Refurbishment	\$ 5,525
	Signage	Signs Hiking Trail Replacement	\$ 11,603
		Signage Subtotal = \$ 17,128.00	
		FY 2024 Annual Expense T	otal = \$ 37,303
	Landscaping & Irrigation	Landscape Decomposed Granite Refurbishment	\$ 1,133
	Lighting	Accent Lights Replacement	\$ 2,136
FY 2025	Signage	Monument Wilderness Estates at High Desert	\$ 5,665
		Refurbishment FY 2025 Annual Expense	Total = \$ 8,934
FY 2026	Asphalt & Concrete	Asphalt Cracksealing & Repairs Michial Emery Trailhead	\$ 2,778
	Landscaping & Irrigation	Irrigation Valves Replacement	\$ 161,644

Year	Category	Item Name	Expense
		Irrigation Water Meters Replacement	\$ 84,220
FY 2026	Landscaping & Irrigation	Landscaping Turf Pinion Point Park Replacement	\$ 24,395
		Landscaping & Irrigation Subtotal = \$ 270,259.00	
	Park Furniture & Elements	Art Restoration	\$ 3,136
		Annual Expense Tota	al = \$ 276,173
	Landscaping & Irrigation	Landscape Decomposed Granite Refurbishment	\$ 1,191
		Monument Desert Highlands at High Desert Refurbishment	\$ 5,955
	Signage	Monument Desert Mountain at High Desert Refurbishment	\$ 893
		Monument High Desert Refurbishment	\$ 23,821
		Monument Highlands at High Desert Refurbishment	\$ 5,955
EV 2027		Monument Mountain Highlands at High Desert Refurbishment	\$ 5,955
FY 2027		Monument Overlook at High Desert Refurbishment	\$ 5,955
		Monument Solterra Refurbishment	\$ 447
		Monument Trailhead at High Desert Refurbishment	\$ 5,955
		Monument West Highlands at High Desert Refurbishment	\$ 5,955
		Monument Wilderness At High Desert Refurbishment	\$ 512
		Signage Subtotal = \$ 61,403.00	
		FY 2027 Annual Expense To	tal = \$ 62,594
EV 2000	Landscaping & Irrigation	Landscaping Plant Material Replacement	\$ 24,423
FY 2028	Painting & Repairs	Metal Fences and Gates Painting	\$ 31,475

Year	Category	Item Name	Expense
		Monument The Aerie Refurbishment	\$ 458
FY 2028	Signage	Monument The Enclave at High Desert Refurbishment	\$ 519
		Signage Subtotal = \$ 977.00	
		FY 2028 Annual Expense To	tal = \$ 56,875
		Asphalt Cracksealing & Repairs Trail	\$ 1,878
		Asphalt Resurfacing Michial Emery Trailhead	\$ 33,802
	Asphalt & Concrete	Asphalt Sealcoating Michial Emery Trailhead	\$ 3,786
		Asphalt Sealcoating Trail	\$ 9,525
		Concrete Sidewalks Repairs	\$ 7,512
		Asphalt & Concrete Subtotal = \$ 56,503.00	
	Fences & Gates	Fence Metal Pipe Rail Replacement	\$ 7,813
	Landscaping & Irrigation	Irrigation Spray Heads Replacement	\$ 1,409
FY 2029		Irrigation System Pinion Point Park Replacement	\$ 20,658
		Irrigation Valve Boxes Replacement	\$ 14,254
		Landscape Decomposed Granite Refurbishment	\$ 1,252
		Landscaping & Irrigation Subtotal = \$ 37,573.00	
	Deinting 9 Densin	Stucco Walls Painting	\$ 201,721
	Painting & Repairs	Stucco Walls Repairs	\$ 13,447
		Painting & Repairs Subtotal = \$ 215,168.00	
	Park Furniture & Elements	Play Equipment Pinion Point Park Replacement	\$ 20,508
	Signage	Monument Michial Emery - Bear Canyon Trailhead Replacement	\$ 470
		FY 2029 Annual Expense Tota	al = \$ 338,035
FY 2030	Signage	Monument The Canyons at High Desert Refurbishment	\$ 481
		Annual Expense	Total = \$ 481

Year	Category	Item Name	Expense
	Asphalt & Concrete	Asphalt Cracksealing & Repairs Michial Emery Trailhead	\$ 3,147
		Irrigation Controllers Replacement	\$ 26,323
FY 2031	Landscaping & Irrigation	Landscape Decomposed Granite Refurbishment	\$ 1,316
	Lanuscaping & imgalion	Landscaping Turf Pinion Point Park Replacement	\$ 27,639
		Landscaping & Irrigation Subtotal = \$ 55,278.00	
		FY 2031 Annual Expense T	otal = \$ 58,425
FY 2032	Fences & Gates	Fence Range Open Range Replacement Future	\$ 101,208
		Annual Expense To	tal = \$ 101,208
	Landscaping & Irrigation	Irrigation Valves Replacement	\$ 192,523
		Landscape Decomposed Granite Refurbishment	\$ 1,384
		Landscaping & Irrigation Subtotal = \$ 193,907.00	
FY 2033	Signage	Monument Desert Song Refurbishment	\$ 519
1 1 2000		Monument Wilderness Canon Refurbishment	\$ 519
		Monument Wilderness Compound Refurbishment	\$ 519
		Signage Subtotal = \$ 1,557.00	
		FY 2033 Annual Expense To	tal = \$ 195,464
		Asphalt Cracksealing & Repairs Trail	\$ 2,128
		Asphalt Resurfacing Trail	\$ 130,166
	Asphalt & Concrete	Asphalt Sealcoating Michial Emery Trailhead	\$ 4,290
- 1/222/		Asphalt Sealcoating Trail	\$ 10,792
FY 2034		Asphalt & Concrete Subtotal = \$ 147,376.00	
	Landarani Oli C	Irrigation Spray Heads Replacement	\$ 1,596
	Landscaping & Irrigation	Irrigation System Common Area Allowance	\$ 7,093
		Landscaping & Irrigation Subtotal = \$ 8,689.00	

Year	Category	Item Name	Expense
FY 2034	Signage	Monument High Desert Park Refurbishment	\$ 7,093
		Annual Expense To	tal = \$ 163,158
	Landscaping & Irrigation	Landscape Decomposed Granite Refurbishment	\$ 1,454
	Lighting	Accent Lights Replacement	\$ 2,742
	Painting & Repairs	Metal Fences and Gates Painting	\$ 37,488
	3 3 4 4	Monument Chaco Ridge & Compound Refurbishment	\$ 545
		Monument Chamisa Trail Refurbishment	\$ 545
		Monument Desert Sky Refurbishment	\$ 545
FY 2035		Monument Pinon Point Refurbishment	\$ 625
1 1 2000	Signage	Monument Sunset Ridge Refurbishment	\$ 545
		Monument The Legends at High Desert Refurbishment	\$ 625
		Monument Tierra Del Oso Refurbishment	\$ 415
		Monument Wilderness Estates at High Desert Refurbishment	\$ 7,272
		Monument Wilderness Village Refurbishment	\$ 545
		Signage Subtotal = \$ 11,662.00	
		FY 2035 Annual Expense To	otal = \$ 53,346
	Asphalt & Concrete	Asphalt Cracksealing & Repairs Michial Emery Trailhead	\$ 3,565
		Irrigation Backflow Preventers Replacement	\$ 64,867
		Irrigation Flow Meters Replacement	\$ 6,710
FY 2036	Landaganing & Irrigation	Irrigation Lateral Line Replacement	\$ 22,368
	Landscaping & Irrigation	Irrigation Main Line Replacement	\$ 160,908
		Landscaping Turf Pinion Point Park Replacement	\$ 31,315
		Landscaping & Irrigation Subtotal = \$ 286,168.00	

Year	Category	Item Name	Expense		
FY 2036	Signage	Monument The Trillium at High Desert Refurbishment	\$ 641		
		Annual Expense To	tal = \$ 290,374		
	Landscaping & Irrigation	Landscape Decomposed Granite Refurbishment	\$ 1,529		
FY 2037	Signage	Monument High Desert Refurbishment	\$ 30,578		
		FY 2037 Annual Expense T			
	Landscaping & Irrigation	Landscaping Plant Material Replacement	\$ 31,352		
FY 2038	Signage	Monument The Enclave at High Desert Refurbishment	\$ 666		
		FY 2038 Annual Expense T	otal = \$ 32,018		
	Asphalt & Concrete	Asphalt Cracksealing & Repairs Trail	\$ 2,411		
		Asphalt Sealcoating Michial Emery Trailhead	\$ 4,860		
		Asphalt Sealcoating Trail	\$ 12,228		
		Concrete Sidewalks Repairs	\$ 9,643		
	Asphalt & Concrete Subtotal = \$ 29,142.00				
		Irrigation Spray Heads Replacement	\$ 1,808		
	Landscaping & Irrigation	Irrigation Valve Boxes Replacement	\$ 18,298		
		Landscape Decomposed Granite Refurbishment	\$ 1,607		
FY 2039		Landscaping & Irrigation Subtotal = \$ 21,713.00			
	Dainting & Danaina	Stucco Walls Painting	\$ 258,947		
	Painting & Repairs	Stucco Walls Repairs	\$ 17,262		
		Painting & Repairs Subtotal = \$ 276,209.00			
		Monument Desert Highlands at High Desert Refurbishment	\$ 8,036		
	Signage	Monument Desert Mountain at High Desert Refurbishment	\$ 1,205		
		Monument Highlands at High Desert Refurbishment	\$ 8,036		

Year	Category	Item Name	Expense
		Monument Mountain Highlands at High Desert Refurbishment	\$ 8,036
		Monument Overlook at High Desert Refurbishment	\$ 8,036
		Monument Solterra Refurbishment	\$ 603
FY 2039	Signage	Monument Trailhead at High Desert Refurbishment	\$ 8,036
		Monument West Highlands at High Desert Refurbishment	\$ 8,036
		Monument Wilderness At High Desert Refurbishment	\$ 691
		Signage Subtotal = \$ 50,715.00	
		FY 2039 Annual Expense To	otal = \$ 377,779
	Landscaping & Irrigation	Irrigation Valves Replacement	\$ 229,300
FY 2040	Signage	Monument The Aerie Refurbishment	\$ 618
	C.g.i.a.g.	FY 2040 Annual Expense To	<u> </u>
		<u>'</u>	. ,
	Asphalt & Concrete	Asphalt Cracksealing & Repairs Michial Emery Trailhead	\$ 4,040
		Irrigation Controllers Replacement	\$ 33,791
	Landscaping & Irrigation	Landscape Decomposed Granite Refurbishment	\$ 1,690
FY 2041	Landocaping & imgation	Landscaping Turf Pinion Point Park Replacement	\$ 35,480
		Landscaping & Irrigation Subtotal = \$ 70,961.00	
	Signage	Monument Michial Emery - Bear Canyon Trailhead Replacement	\$ 634
		Annual Expense	Γotal = \$ 75,635
	Painting & Repairs	Metal Fences and Gates Painting	\$ 44,649
FY 2042	Signage	Monument The Canyons at High Desert Refurbishment	\$ 650

Year	Category	Item Name	Expense
		FY 2042 Annual Expense	Γotal = \$ 45,299
			0.4.770
FY 2043	Landscaping & Irrigation	Landscape Decomposed Granite Refurbishment	\$ 1,776
	Signage	Monument Desert Song Refurbishment	\$ 666
		FY 2043 Annual Expense	Total = \$ 2,442
		Asphalt Cracksealing & Repairs Trail	\$ 2,731
	Asphalt & Concrete	Asphalt Sealcoating Michial Emery Trailhead	\$ 5,507
		Asphalt Sealcoating Trail	\$ 13,854
		Asphalt & Concrete Subtotal = \$ 22,092.00	
	Landananian O lurination	Irrigation Spray Heads Replacement	\$ 2,049
FY 2044	Landscaping & Irrigation	Irrigation System Common Area Allowance	\$ 9,105
		Landscaping & Irrigation Subtotal = \$ 11,154.00	
	Park Furniture & Elements	Play Equipment Pinion Point Park Replacement	\$ 29,828
	Signage	Monument High Desert Park Refurbishment	\$ 9,105
		Signs Hiking Trail Replacement	\$ 19,120
		Signage Subtotal = \$ 28,225.00	
		FY 2044 Annual Expense	Total = \$ 91,299
	Landscaping & Irrigation	Landscape Decomposed Granite Refurbishment	\$ 1,867
FY 2045	Lighting	Accent Lights Replacement	\$ 3,519
F1 2045	Signage	Monument Wilderness Estates at High Desert Refurbishment	\$ 9,335
		FY 2045 Annual Expense	Γotal = \$ 14,721
	Asphalt & Concrete	Asphalt Cracksealing & Repairs Michial Emery Trailhead	\$ 4,577
- \/ 22 : -		Irrigation Water Meters Replacement	\$ 138,783
FY 2046	Landscaping & Irrigation	Landscaping Turf Pinion Point Park Replacement	\$ 40,199
		Landscaping & Irrigation Subtotal = \$ 178,982.00	

Year	Category	Item Name	Expense
FY 2046	Park Furniture & Elements	Art Restoration	\$ 5,168
		Annual Expense To	tal = \$ 188,727
	Landaganing & Irrigation	Irrigation Valves Replacement	\$ 273,103
	Landscaping & Irrigation	Landscape Decomposed Granite Refurbishment	\$ 1,963
		Landscaping & Irrigation Subtotal = \$ 275,066.00	
FY 2047	Painting & Repairs	Ramada Chamisa Park Refurbishment	\$ 4,259
		Monument Chaco Ridge & Compound Refurbishment	\$ 736
		Monument Chamisa Trail Refurbishment	\$ 736
		Monument Desert Sky Refurbishment	\$ 736
	Signage	Monument High Desert Refurbishment	\$ 39,253
		Monument Pinon Point Refurbishment	\$ 844
		Monument Sunset Ridge Refurbishment	\$ 736
		Monument The Legends at High Desert Refurbishment	\$ 844
		Monument Tierra Del Oso Refurbishment	\$ 559
		Monument Wilderness Village Refurbishment	\$ 736
		Signage Subtotal = \$ 45,180.00	
		FY 2047 Annual Expense To	tal = \$ 324,505
	Landscaping & Irrigation	Landscaping Plant Material Replacement	\$ 40,246
	Painting & Repairs	Ramada Pinon Point Park Refurbishment	\$ 3,385
EV 2040		Monument The Enclave at High Desert Refurbishment	\$ 855
FY 2048	Signage	Monument Wilderness Canon Refurbishment	\$ 755
		Monument Wilderness Compound Refurbishment	\$ 755
		Signage Subtotal = \$ 2,365.00	
		FY 2048 Annual Expense T	otal = \$ 45,996

Year	Category	Item Name	Expense
		Asphalt Cracksealing & Repairs Trail	\$ 3,095
	Apphalt & Canarata	Asphalt Sealcoating Michial Emery Trailhead	\$ 6,239
	Asphalt & Concrete	Asphalt Sealcoating Trail	\$ 15,697
		Concrete Sidewalks Repairs	\$ 12,379
		Asphalt & Concrete Subtotal = \$ 37,410.00	
		Irrigation Spray Heads Replacement	\$ 2,321
FY 2049	Landscaping & Irrigation	Irrigation Valve Boxes Replacement	\$ 23,489
		Landscape Decomposed Granite Refurbishment	\$ 2,063
		Landscaping & Irrigation Subtotal = \$ 27,873.00	
	Painting & Repairs	Metal Fences and Gates Painting	\$ 53,178
		Stucco Walls Painting	\$ 332,408
		Stucco Walls Repairs	\$ 22,158
		Painting & Repairs Subtotal = \$ 407,744.00	
		FY 2049 Annual Expense To	otal = \$ 473,027
	Asphalt & Concrete	Asphalt Cracksealing & Repairs Michial Emery Trailhead	\$ 5,186
		Fence Metal Perimeter Desert Mountain Replacement	\$ 6,598
		Fence Metal Perimeter Solterra Replacement	\$ 1,241
		Fence Metal Perimeter The Canyons Replacement	\$ 141,474
FY 2051	Fences & Gates	Fence Metal Perimeter The Enclave Replacement	\$ 2,707
		Fence Metal Perimeter The Legends Replacement	\$ 2,982
		Fence Metal Perimeter The Trillium Replacement	\$ 17,837
		Fence Metal Perimeter Tierra Del Oso Replacement	\$ 68,232

Year	Category	Item Name	Expense
FY 2051	Fences & Gates	Fence Metal Perimeter Wilderness Replacement	\$ 7,634
		Fence Metal Perimeter Wilderness Compound Replacement	\$ 6,050
	Fences & Gates Subtotal = \$ 254,755.00		
	Landscaping & Irrigation	Irrigation Backflow Preventers Replacement	\$ 94,345
		Irrigation Controllers Replacement	\$ 43,377
		Irrigation Flow Meters Replacement	\$ 9,760
		Irrigation Lateral Line Replacement	\$ 32,533
		Landscape Decomposed Granite Refurbishment	\$ 2,169
		Landscaping Turf Pinion Point Park Replacement	\$ 45,546
	Landscaping & Irrigation Subtotal = \$ 227,730.00		
	Park Furniture & Elements	Park Furniture Chamisa Park Replacement	\$ 2,440
		Park Furniture Medara Park Replacement	\$ 4,988
		Park Furniture Pinion Point Park Replacement	\$ 1,735
	Park Furniture & Elements Subtotal = \$ 9,163.00		
	Signage	Monument Desert Highlands at High Desert Refurbishment	\$ 10,844
		Monument Desert Mountain at High Desert Refurbishment	\$ 1,627
		Monument Highlands at High Desert Refurbishment	\$ 10,844
		Monument Mountain Highlands at High Desert Refurbishment	\$ 10,844
		Monument Overlook at High Desert Refurbishment	\$ 10,844
		Monument Solterra Refurbishment	\$ 813
		Monument The Trillium at High Desert Refurbishment	\$ 933

Year	Category	Item Name	Expense
FY 2051	Signage	Monument Trailhead at High Desert Refurbishment	\$ 10,844
		Monument West Highlands at High Desert Refurbishment	\$ 10,844
		Monument Wilderness At High Desert Refurbishment	\$ 933
		Signs Pet Waste Stations Replacement	\$ 37,955
	Signage Subtotal = \$ 107,325.00		
FY 2051 Annual Expense Total = \$ 604,159			